

WX3100-T0 Generic

Firmware Release Note

V5.50(ABVL.4.9)C0

Date: Dec 19, 2025

Author: Neil Chen

Reviewer:

THIS DOCUMENT CONTAINS PROPRIETARY TECHNICAL INFORMATION THAT IS THE PROPERTY OF THE Zyxel AND SHOULD NOT BE DISCLOSED TO OTHERS IN WHOLE OR IN PART, REPRODUCED, COPIED, OR USED AS BASIS FOR DESIGN, MANUFACTURING OR SALE OF APPARATUS WITHOUT WRITTEN PERMISSION OF Zyxel.

TABLE OF CONTENTS

REVISION HISTORY.....	5
SUPPORTED PLATFORMS:.....	7
VERSIONS:	7
NOTES:.....	7
KNOWN ISSUES.....	9
MODIFICATIONS IN 5.50(ABVL.4.9)C0	10
MODIFICATIONS IN 5.50(ABVL.4.9)B1	10
MODIFICATIONS IN 5.50(ABVL.4.8)C0	10
MODIFICATIONS IN 5.50(ABVL.4.8)B2	10
MODIFICATIONS IN 5.50(ABVL.4.8)B1	11
MODIFICATIONS IN 5.50(ABVL.4.7)C0	12
MODIFICATIONS IN 5.50(ABVL.4.7)B2	12
MODIFICATIONS IN 5.50(ABVL.4.7)B1	12
MODIFICATIONS IN 5.50(ABVL.4.6)C0	13
MODIFICATIONS IN 5.50(ABVL.4.6)B2	13
MODIFICATIONS IN 5.50(ABVL.4.6)B1	13
MODIFICATIONS IN 5.50(ABVL.4.4)C0	14
MODIFICATIONS IN 5.50(ABVL.4.4)B1	14
MODIFICATIONS IN 5.50(ABVL.4.3)C0	14
MODIFICATIONS IN 5.50(ABVL.4.3)B1	14
MODIFICATIONS IN 5.50(ABVL.4.2)C0	15
MODIFICATIONS IN 5.50(ABVL.4.2)B1	15
MODIFICATIONS IN 5.50(ABVL.4.1)C0	15
MODIFICATIONS IN 5.50(ABVL.4.1)B1	15
MODIFICATIONS IN 5.50(ABVL.4)C0.....	16
MODIFICATIONS IN 5.50(ABVL.4)B3	16

MODIFICATIONS IN 5.50(ABVL.4)B2	16
MODIFICATIONS IN 5.50(ABVL.4)B1	17
MODIFICATIONS IN 5.50(ABVL.3)C0.....	17
MODIFICATIONS IN 5.50(ABVL.3)B5	17
MODIFICATIONS IN 5.50(ABVL.3)B4	18
MODIFICATIONS IN 5.50(ABVL.3)B3	18
MODIFICATIONS IN 5.50(ABVL.3)B2	19
MODIFICATIONS IN 5.50(ABVL.3)B1	19
MODIFICATIONS IN 5.50(ABVL.2)C0.....	19
MODIFICATIONS IN 5.50(ABVL.2)B4	20
MODIFICATIONS IN 5.50(ABVL.2)B3	20
MODIFICATIONS IN 5.50(ABVL.2)B2	20
MODIFICATIONS IN 5.50(ABVL.2)B1	21
MODIFICATIONS IN 5.50(ABVL.1.1)C0	21
MODIFICATIONS IN 5.50(ABVL.1.1)B1	22
MODIFICATIONS IN 5.50(ABVL.1)C0.....	22
MODIFICATIONS IN 5.50(ABVL.1)B4	22
MODIFICATIONS IN 5.50(ABVL.1)B3	22
MODIFICATIONS IN 5.50(ABVL.1)B2	23
MODIFICATIONS IN 5.50(ABVL.1)B1	24
MODIFICATIONS IN 5.50(ABVL.0)C0.....	24
MODIFICATIONS IN 5.50(ABVL.0)B10	24
MODIFICATIONS IN 5.50(ABVL.0)B9	25
MODIFICATIONS IN 5.50(ABVL.0)B8	25
MODIFICATIONS IN 5.50(ABVL.0)B7	25
MODIFICATIONS IN 5.50(ABVL.0)B6	26
MODIFICATIONS IN 5.50(ABVL.0)B5	26

MODIFICATIONS IN 5.50(ABVL.0)B4 27

MODIFICATIONS IN 5.50(ABVL.0)B3 28

MODIFICATIONS IN 5.50(ABVL.0)B2 30

MODIFICATIONS IN 5.50(ABVL.0)B1 30

Revision History

Date	Release	Author	Description
2020/08/06	1.0	Linda Huang	FW release for V5.50(ABVL.0)b1
2020/08/28	1.1	Joanna Su	FW release for V5.50(ABVL.0)b2
2020/10/12	1.2	Joanna Su	FW release for V5.50(ABVL.0)b3
2020/11/13	1.3	Joanna Su	FW release for V5.50(ABVL.0)b4
2021/01/28	1.4	Joanna Su	FW release for V5.50(ABVL.0)b5
2021/03/08	1.5	Joanna Su	FW release for V5.50(ABVL.0)b6
2021/05/07	1.6	Joanna Su	FW release for V5.50(ABVL.0)b7
2021/06/10	1.7	Joanna Su	FW release for V5.50(ABVL.0)b8
2021/07/30	1.8	Joanna Su	FW release for V5.50(ABVL.0)b9
2021/08/27	1.9	Joanna Su	FW release for V5.50(ABVL.0)b10
2021/09/10	1.10	Joanna Su	FW release for V5.50(ABVL.0)C0
2021/10/4	2.0	Joanna Su	FW release for V5.50(ABVL.1)b1
2021/12/17	2.1	Neil Chen	FW release for V5.50(ABVL.1)b2
2022/02/10	2.2	Neil Chen	FW release for V5.50(ABVL.1)b3
2022/02/24	2.3	Neil Chen	FW release for V5.50(ABVL.1)b4
2022/03/03	2.4	Neil Chen	FW release for V5.50(ABVL.1)C0
2022/11/07	3.0	Neil Chen	FW release for V5.50(ABVL.1.1)b1
2022/11/07	3.1	Neil Chen	FW release for V5.50(ABVL.1.1)C0
2022/11/25	3.2	Neil Chen	FW release for V5.50(ABVL.2)b1
2023/02/24	3.3	Neil Chen	FW release for V5.50(ABVL.2)b2
2023/03/31	3.4	Neil Chen	FW release for V5.50(ABVL.2)b3
2023/05/03	3.5	Neil Chen	FW release for V5.50(ABVL.2)b4
2023/05/12	3.6	Neil Chen	FW release for V5.50(ABVL.2)C0
2023/06/02	4.0	Neil Chen	FW release for V5.50(ABVL.3)b1
2023/07/04	4.1	Neil Chen	FW release for V5.50(ABVL.3)b2
2023/08/21	4.2	Neil Chen	FW release for V5.50(ABVL.3)b3
2023/09/01	4.3	Neil Chen	FW release for V5.50(ABVL.3)b4
2023/10/13	4.4	Neil Chen	FW release for V5.50(ABVL.3)b5
2023/10/24	4.5	Neil Chen	FW release for V5.50(ABVL.3)C0
2023/11/16	5.0	Neil Chen	FW release for V5.50(ABVL.4)b1
2023/12/15	5.1	Neil Chen	FW release for V5.50(ABVL.4)b2

2024/01/19	5.2	Neil Chen	FW release for V5.50(ABVL.4)b3
2024/02/19	5.3	Neil Chen	FW release for V5.50(ABVL.4)C0
2024/03/08	5.4	Neil Chen	FW release for V5.50(ABVL.4.1)b1
2024/03/08	5.5	Neil Chen	FW release for V5.50(ABVL.4.1)C0
2024/05/28	5.6	Neil Chen	FW release for V5.50(ABVL.4.2)b1
2024/05/28	5.7	Neil Chen	FW release for V5.50(ABVL.4.2)C0
2024/06/12	5.8	Neil Chen	FW release for V5.50(ABVL.4.3)b1
2024/06/12	5.9	Neil Chen	FW release for V5.50(ABVL.4.3)C0
2024/09/27	5.10	Neil Chen	FW release for V5.50(ABVL.4.4)b1
2024/09/27	5.11	Neil Chen	FW release for V5.50(ABVL.4.4)C0
2024/12/13	5.12	Neil Chen	FW release for V5.50(ABVL.4.6)b1
2025/01/10	5.13	Neil Chen	FW release for V5.50(ABVL.4.6)b2
2025/02/13	5.14	Neil Chen	FW release for V5.50(ABVL.4.6)C0
2025/05/13	5.15	Neil Chen	FW release for V5.50(ABVL.4.7)b1
2025/06/04	5.16	Neil Chen	FW release for V5.50(ABVL.4.7)b2
2025/06/04	5.17	Neil Chen	FW release for V5.50(ABVL.4.7)C0
2025/08/22	5.18	Neil Chen	FW release for V5.50(ABVL.4.8)b1
2025/09/23	5.19	Neil Chen	FW release for V5.50(ABVL.4.8)b2
2025/09/23	5.20	Neil Chen	FW release for V5.50(ABVL.4.8)C0
2025/12/19	5.21	Neil Chen	FW release for V5.50(ABVL.4.9)b1
2025/12/19	5.22	Neil Chen	FW release for V5.50(ABVL.4.9)C0

WX3100-T0 Generic V5.50(ABVL.4.9)C0 Release Note

Date: Dec 19, 2025

Supported Platforms:

Zyxel WX3100-T0

Versions:

Bootbase version : V1.46 | 05/07/2021 11:40:00

Firmware version : V5.50(ABVL.4.9)C0

Kernel version: 3.18.21

WLAN code version: 7.4.0.0_EN7516G

app-agent: 3.0

netprobe: 4.0

zy1905: 3.0

Notes:

Public Domain Software Announcements

Open Source Used In Product	Version	From (Source)	License Terms	Modified / Used
atftp	0.7.1	https://sourceforge.net/projects/atftp/	GPLv2	Modified
bridge-Utills	1.0.6	https://git.kernel.org/pub/scm/linux/kernel/git/shemminger/bridge-utils.git/	GPLv2	Modified
busybox	1.20.1	https://busybox.net/	GPLv2	Modified
clinkc	2.4	https://sourceforge.net/projects/clinkc/	BSD	Modified
conntrack-tools	1.4.3	https://git.netfilter.org/conntrack-tools/	GPLv2	Used
dropbear	2018.76	https://github.com/mkj/dropbear	MIT	Modified
ebtables	2.0.8-2	https://git.netfilter.org/ebtables/	GPLv2	Modified
eventlog	0.2.10	https://github.com/balabit/eventlog	BSD	Used
expat	2.7.1	https://github.com/libexpat/libexpat	MIT	Used
ez-ipupdate	3.0.11b8	http://ez-ipupdate.com/	GPLv2	Modified
gettext	0.16.1	http://www.gnu.org/software/gettext/	GPLv2	Used
glib	2.37.7	http://www.gtk.org/	LGPLv2	Used
iproute2	2.6.33	https://github.com/shemminger/iproute2	GPLv2	Modified
iptables	1.4.10	https://git.netfilter.org/iptables/	GPLv2	Modified
jpegsrcc	v9a	http://www.iijg.org/	IJG	Used
json-c	0.13.1	https://github.com/json-c/json-c/downloads	MIT	Modified
libedit	20080712-2.11	http://pkgs.fedoraproject.org/repo/pkgs/libedit/libedit-20080712-2.11.tar.gz/	BSD	Modified
libffi	3.0.11	http://pkgs.fedoraproject.org/repo/pkgs/libffi/libffi-3.0.11.tar.gz/	MIT	Used
libiconv	1.11.1	http://www.gnu.org/software/libiconv/	LGPLv2	Modified
libnetfilter_conntrack	1.0.4	https://git.netfilter.org/libnetfilter_conntrack/	GPLv2	Used
libnetfilter_queue	1.0.2	https://git.netfilter.org/libnetfilter_queue/	GPLv2	Used
libnfnetlink	1.0.1	https://git.netfilter.org/libnfnetlink/	GPLv2	Used

libnl-tiny	0.1	https://github.com/openwrt/openwrt/tree/master/package/libs/libnl-tiny	GPLv2/LGPLv2.1	Used
libpcap	1.1.1	www.tcpdump.org	BSD	Used
libtool	2.4	http://www.gnu.org/software/libtool/	GPLv2	Used
libstrophe	0.10.0	https://github.com/strophe/libstrophe	GPLv3	Used
Linux/Arm Kernel	3.18.21		GPLv2	Modified
logrotate	3.7.1	https://launchpad.net/ubuntu/hardy/i386/logrotate/	GPLv2	Modified
ncurses	5.7	http://ftp.gnu.org/pub/gnu/ncurses/	MIT	Modified
ntfs-3g	2013.1.13	http://ntfs-3g.org	GPLv2/LGPLv2	Used
ntpcclient	2007_365	http://doolittle.icarus.com/ntpcclient/	GPLv2	Modified
openssl	1.1.1f	http://www.openssl.org	OpenSSL	Modified
popt	1.16	http://rpm5.org/files/popt/	MIT	Modified
pure-ftpd	1.0.30	http://pureftpd.org	ISC/BSD	Modified
readline	5.2	http://cnswww.cns.cwru.edu/php/chet/readline/rltop.html	GPLv2	Used
sqlite	3.6.23.1	http://www.sqlite.org/	Public Domain License	Used
syslog-ng	2.0.10	https://github.com/balabit/syslog-ng	GPLv2	Used
tcpdump	4.2.1	http://www.tcpdump.org/	BSD	Used
udhcp	0.9.8	http://udhcp.busybox.net/	GPLv2	Modified
util-linux	2.21.2	https://github.com/karelzak/util-linux/	GPLv2	Used
wide-dhcpv6	20080615	https://sourceforge.net/projects/wide-dhcpv6/	BSD	Modified
zlib	1.2.7	https://github.com/madler/zlib	zlib	Used

Known issues

Modules	Issue	Risk Impact Information

Modifications in 5.50(ABVL.4.9)C0

Based on V5.50(ABVL.4.9)b1 to release V5.50(ABVL.4.9)C0

Modifications in 5.50(ABVL.4.9)b1

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
System	<ol style="list-style-type: none">1. [#245995][CVE-2025-11845, CVE-2025-11846, CVE-2025-11847, CVE-2025-11848] Zyxel-SI-1638 [Vulnerability] Multiple potential null pointer dereference vulnerabilities in the CGI program2. [#246736][CVE-2025-13942、CVE-2025-13943] Zyxel-SI-1644 [Vulnerability] Command injection vulnerabilities in zupnp and zhttpd binaries in customized firmware

Modifications in 5.50(ABVL.4.8)C0

Based on V5.50(ABVL.4.8)b2 to release V5.50(ABVL.4.8)C0

Modifications in 5.50(ABVL.4.8)b2

● Feature Enhancement

Modified Modules	Features Enhancement List

--	--

- **Bug Fixed**

Modified Modules	Bug Fixed List
System	1. [#239770] [CVE-2025-6599] Zyxel-SI-1621 [Vulnerability] Slow read DoS vulnerability on the zhttpd web server

Modifications in 5.50(ABVL.4.8)b1

- **Feature Enhancement**

Modified Modules	Features Enhancement List

- **Bug Fixed**

Modified Modules	Bug Fixed List
System	<ol style="list-style-type: none">1. [#239769] [CVE-2025-6599] Zyxel-SI-1616 [Vulnerability] Slow HTTP DoS vulnerability in the DX3301-T02. [#239770] [CVE-2025-6599] Zyxel-SI-1621 [Vulnerability] Slow read DoS vulnerability on the zhttpd web server3. [#239916] [CVE-2025-8693] Zyxel-SI-1624 [Vulnerability] A post-authentication command injection vulnerability in the certificate upload CGI program of DX3300-T0 and VMG3925-B10B4. [#239932] Zyxel-SI-1612 Improper privilege management in VMG4005-B50A5. [#239934] [CVE-2025-20631 、 CVE-2025-20632 、 CVE-2025-20633] Possible out-of-bounds write in MTK WLAN driver

Modifications in 5.50(ABVL.4.7)C0

Based on V5.50(ABVL.4.7)b2 to release V5.50(ABVL.4.7)C0

Modifications in 5.50(ABVL.4.7)b2

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
System	1. [#235294] Zyxel-SI-1605 [Vulnerability] The libexpat open source library is vulnerable to DoS attacks through stack overflow

Modifications in 5.50(ABVL.4.7)b1

● Feature Enhancement

Modified Modules	Features Enhancement List
System	1. [#232902] EN18031 OPAL20 product compliance release 2. [#232904] WEB GUI meets the request of Europe EAA (European Accessibility Act)

● Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.50(ABVL.4.6)C0

Based on V5.50(ABVL.4.6)b2 to release V5.50(ABVL.4.6)C0

Modifications in 5.50(ABVL.4.6)b2

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
MPro Mesh	1. [#226051] [MPro Mesh][Zyxel One_Agent] WiFi clients will show in Wired page.

Modifications in 5.50(ABVL.4.6)b1

● Feature Enhancement

Modified Modules	Features Enhancement List
App	1. [#225007] [WX3100-T0] Support Zyxel one app

● Bug Fixed

Modified Modules	Bug Fixed List
System	1. [#225010] Zyxel-SI-1592 [Vulnerability] Post-authentication command injection vulnerability in the email sending function

Modifications in 5.50(ABVL.4.4)C0

Based on V5.50(ABVL.4.4)b1 to release V5.50(ABVL.4.4)C0

Modifications in 5.50(ABVL.4.4)b1

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
System	1. [#219836] [CVE-2024-8748] [Zyxel-SI-1576] [Vulnerability] Unauthenticated buffer overflow in VMG8825-T50 2. [#220317] [CVE-2024-20017] Improper input validation in wlan service

Modifications in 5.50(ABVL.4.3)C0

Based on V5.50(ABVL.4.3)b1 to release V5.50(ABVL.4.3)C0

Modifications in 5.50(ABVL.4.3)b1

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified	Bug Fixed List
----------	----------------

Modules	
System	1. [#212600] Zyxel-SI-1559 [Vulnerability] Multiple authenticated buffer overflow vulnerabilities in VMG8825-T50

Modifications in 5.50(ABVL.4.2)C0

Based on V5.50(ABVL.4.2)b1 to release V5.50(ABVL.4.2)C0

Modifications in 5.50(ABVL.4.2)b1

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
Reboot	1. [#211666] [eITS#240500742] Ex3300 reboots periodically
System	1. [#211702] Zyxel-SI-1557 [Vulnerability] Unauthenticated heap buffer overflow in the libclinkc library

Modifications in 5.50(ABVL.4.1)C0

Based on V5.50(ABVL.4.1)b1 to release V5.50(ABVL.4.1)C0

Modifications in 5.50(ABVL.4.1)b1

● Feature Enhancement

Modified	Features Enhancement List
----------	---------------------------

Modules	

● Bug Fixed

Modified Modules	Bug Fixed List
System	1. [#207180] [Vulnerability] Zyxel-SI-1536 [Vulnerability] Buffer overflow vulnerability in the "traceroute" command of DX3300-T1 CPE --- for WX3100-T0

Modifications in 5.50(ABVL.4)C0

Based on V5.50(ABVL.4)b3 to release V5.50(ABVL.4)C0

Modifications in 5.50(ABVL.4)b3

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
GUI	1. [#203871] [GUI]Change Extender Icon
System	1. [#201615] [System] Set admin password should contain special characters

Modifications in 5.50(ABVL.4)b2

● Feature Enhancement

Modified	Features Enhancement List
----------	---------------------------

Modules	

● Bug Fixed

Modified Modules	Bug Fixed List
MPro Mesh	1. [#194850] [MPro Mesh] By default do WPS on-boarding will random fail.

Modifications in 5.50(ABVL.4)b1

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
System	1. [#195758] [Vulnerability] Zyxel-SI-1506 [Vulnerability] Post-authentication buffer overflow in VMG3625-T50B 2. [#195764] Zyxel-SI-1498 [Vulnerability] WPS vulnerability on DX3301-T0 CPE in WLAN

Modifications in 5.50(ABVL.3)C0

Based on V5.50(ABVL.3)b5 to release V5.50(ABVL.3)C0

Modifications in 5.50(ABVL.3)b5

● Feature Enhancement

Modified	Features Enhancement List

Modules	

- **Bug Fixed**

Modified Modules	Bug Fixed List
MPro Mesh	1. [WX3100][NR5103E] 3b2_H0, Link LED issue and Incorrect topology if STA connect agent by Wi-Fi 2.4G

Modifications in 5.50(ABVL.3)b4

- **Feature Enhancement**

Modified Modules	Features Enhancement List

- **Bug Fixed**

Modified Modules	Bug Fixed List
MPro Mesh	1. [#196662] [MPro Mesh] ZyPark Multy Pro stress, after about 4 hours, the wifi clients are unable to connect MESH network.

Modifications in 5.50(ABVL.3)b3

- **Feature Enhancement**

Modified Modules	Features Enhancement List

- **Bug Fixed**

Modified Modules	Bug Fixed List
MPro Mesh	1. [#194849] [MPro Mesh] Connectivity page topology

	disapper after on-boarding RP_agent.
--	--------------------------------------

Modifications in 5.50(ABVL.3)b2

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
LED	1. The WPS LED doesn't blink when push the WPS button before onboarding to gateway

Modifications in 5.50(ABVL.3)b1

● Feature Enhancement

Modified Modules	Features Enhancement List
WLAN	1. Support Mesh R2
MproMesh	1. Support MproMesh 3.0

● Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.50(ABVL.2)C0

Based on V5.50(ABVL.2)b4 to release V5.50(ABVL.2)C0

Modifications in 5.50(ABVL.2)b4

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
System	1. [#187652] [System] Auto online upgrade(FOTA)should be disabled.

Modifications in 5.50(ABVL.2)b3

● Feature Enhancement

Modified Modules	Features Enhancement List
Firmware Upgrade	1. [FOTA] Firmware upgrade via FOTA requirement.

● Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.50(ABVL.2)b2

● Feature Enhancement

Modified Modules	Features Enhancement List

Note. After 5.50(ABVL.2)b1, WPS trigger is changed to feature #153990

● Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.50(ABVL.2)b1

● Feature Enhancement

Modified Modules	Features Enhancement List
WPS	1. [#153990] [eITS Ticket #210900469][Altibox][ZYX-254] WX3401, Change WPS button when wireless backhaul is in use
WLAN	1. [#154530] WX3100-T0 - Guest Wi-Fi is not enabled on Extenders when you enable it in MPro Mesh APP
GUI	1. [#158609] WX3100/WX3401, Feature Request GUI Topology View
TR-069	1. [#159862] WX3100-T0 - V5.50(ABVL.0)C0 - Retrieve LAN Host Host Type - TR069 testing

● Bug Fixed

Modified Modules	Bug Fixed List
WLAN	1. [#152621] WX3100-T0 - v5.50(ABVL.0)b8 - MPro Mesh App reports all connected devices as wired not wireless
GUI	1. [#177441] Supervisor password cannot be changed from WebUI with 1C0 firmware

Modifications in 5.50(ABVL.1.1)C0

Based on V5.50(ABVL.1.1)b1 to release V5.50(ABVL.1.1)C0

Modifications in 5.50(ABVL.1.1)b1

● Bug Fixed

Modified Modules	Bug Fixed List
System	1. [#177431] [Zyxel-SI-1433 [Vulnerability] Buffer overflow vulnerabilities and command injection vulnerability, for WX3100-T0

Modifications in 5.50(ABVL.1)C0

Based on V5.50(ABVL.1)b4 to release V5.50(ABVL.1)C0

Modifications in 5.50(ABVL.1)b4

● Bug Fixed

Modified Modules	Bug Fixed List
TR-069	1. [#161367] WX3100-T0 / Config Issue after XMPP config via TR-069 (AX69)

Modifications in 5.50(ABVL.1)b3

● Feature Enhancement

Modified Modules	Features Enhancement List
TR-069	1. [#159862] WX3100-T0 - V5.50(ABVL.0)C0 - Retrieve LAN Host Host Type - TR069 testing 2. [#159859] WX3100-T0 - V5.50(ABVL.0)C0 - Retrieve LAN Ethernet Port Speed - TR069 testing

DHCP	1. [#158732] WX3100, Request opt 43 to receive ACS URL from CPE, with auto-activation of CWMP
------	---

● Bug Fixed

Modified Modules	Bug Fixed List
TR-069	1. [#159081] WX3100-T0 - V5.50(ABVL.0)C0 - Retrieve IP Ping Results - TR069 testing
Home Device	1. [#152620] WX3100-T0 - Ethernet LAN clients connected to a Repeater are not listed in the MPro Mesh App
Router Information	1. [#159441] [Nology] Set SSID to custom one - SSID is configured twice

Modifications in 5.50(ABVL.1)b2

● Feature Enhancement

Modified Modules	Features Enhancement List
WiFi	1. [#149556] v5.50(AVBL.0)b7 - WX3100-T0 - MPro Mesh App - Does not resolve hostnames only MAC addresses
GUI	1. [#149554] v5.50(AVBL.0)b7 - WX3100-T0 - ROM-D functionality contains no Save option
SYSTEM	1. [#155334] [Feature] WX3100-T0, cancel signal too strong Amber LED

● Bug Fixed

Modified Modules	Bug Fixed List
WLAN	1. #211000170 - WX3100, iPhone 11 Pro disconnected after idle/sleep 2. [#152621] WX3100-T0 - v5.50(ABVL.0)b8 - MPro Mesh App reports all connected devices as wired not wireless 3. [#153010] WX3100-T0 Mpro Mesh - Set SSID to custom one - SSID is configured twice

SYSTEM	2. [#156203] WX3100-T0 / IPv6 / No Default Route 3. [#157879] TR-069 interface binding unstable with IPv6
--------	--

Modifications in 5.50(ABVL.1)b1

● Feature Enhancement

Modified Modules	Features Enhancement List
	1. [#153239] support Lifemote agent TR-181 parameters 2. [#155002] support pre-paired for Twin-pack

● Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.50(ABVL.0)C0

Based on V5.50(ABVL.0)b10 to release V5.50(ABVL.0)C0

Modifications in 5.50(ABVL.0)b10

● Feature Enhancement

Modified Modules	Features Enhancement List
	1. Remove A134 NULL MAC STA patch 2. Memory leak in mpad 3. Block weather channels 4. [A130] Cannot connect back after Radar detected 5. IgmpSnEnable to per SSID (5G WLAN PC play IPTV will be broken picture severe)

● Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.50(ABVL.0)b9

● Bug Fixed

Modified Modules	Bug Fixed List
WLAN	<ol style="list-style-type: none"> 1. [#143001][MPro Mesh] AP roaming will generate more ping loss, iPhone SE will disconnect 2. [#149938][MPro Mesh] RP controller paired extender_RP agent will occurs call trace 3. [#150061][MPro Mesh_Agent] According APP 2.2 Feature Enhancement, Generic FW does not support MESH Up/Down 4. [#150072][MPro Mesh_Agent] The connection type of Extender-RP repeated switch to WiFi or Ethernet type 5. [#150169][MPro Mesh] ZyPark MPro stress test environment, Stress testing it will cause Extender_RP1 to reboot

Modifications in 5.50(ABVL.0)b8

● Bug Fixed

Modified Modules	Bug Fixed List
WLAN	<ol style="list-style-type: none"> 1. [143001][MPro Mesh] AP roaming will generate more ping loss, iPhone SE will disconnect 2. [143471][MPro Mesh] ZyPark MPro stress test environment, Stress testing will cause "ZyMAPSteer" daemon disappear

Modifications in 5.50(ABVL.0)b7

● Bug Fixed

Modified Modules	Bug Fixed List

WLAN	<ol style="list-style-type: none"> 1. [143001][MPro Mesh] AP roaming will generate more ping loss, iPhone SE will disconnect 2. [143471][MPro Mesh] ZyPark MPro stress test environment, Stress testing will cause "ZyMAPSteer" daemon disappear
------	--

Modifications in 5.50(ABVL.0)b6

● Bug Fixed

Modified Modules	Bug Fixed List
WLAN	<ol style="list-style-type: none"> 1. [#139522][MPro Mesh_Agent] When client connected to guest WiFi , that client can not use APP 2. [#143001][MPro Mesh] AP roaming will generate more ping loss, iPhone SE will disconnect 3. [#140235][Stress] WX3100 will call trace after multi clients connect over night stress 4. [#135285][MPro Mesh] Onboarding Extender will enable extender guest wifi by itself 5. [#137435][MPro Mesh_Agent for iOS]All Extender change to normal wifi clients in Devices list page when let all Extender disconnect and connect again or reboot controller

Modifications in 5.50(ABVL.0)b5

● Feature Enhancement

Modified Modules	Features Enhancement List
WLAN	<ol style="list-style-type: none"> 1. [Telenor] WPS IOP issue with EX3301-T0 with WX3100-T0 verification <ol style="list-style-type: none"> 1.1 Disable power saving mode 2. Update power table for CE certificate
Security	<ol style="list-style-type: none"> 1. [#140744][BUGFIX][Common][CVE-2020-1971][Openssl]Correctly compare EdiPartyName in GENERAL_NAME_cmp()

● Bug Fixed

Modified Modules	Bug Fixed List
WLAN	<ol style="list-style-type: none"> 1. [#139035][MPro Mesh] Sometimes extender cannot sync new wifi setting from controller. (Rate: 2/5) 2. [#138948][MPro Mesh] WX3100_RP Agent will disconnect/connect repeatedly after WX3100_AP controller do auto configure. 3. [#139389][MPro Mesh_Agent] Add extender success, but all extender did not show in APP Home Page 4. [#135795][MPro Mesh] AP roaming test fail 5. [#135723][MPro Mesh] Band steering, Wifi client information disappears, Returning to the controller will not steer wifi client to 5G. 6. [#138860][Wireless] Key in AP SSID/password on Operating Mode page, WX3100 connect to gateway, but ip address still keep on 192.168.1.2 7. [#139291][MPro Mesh] AP_Agent connected RP_Controller, the RP_Controller will disconnect and cannot connect back non_Mesh GW wifi. 8. [#138857][Wireless] After AP List connect to gateway, ip address still keep on 192.168.1.2 9. [#138969][Wireless] After disable 2.4G and 5G, CPE will call trace and can't reconnect to GW. 10. [#135139][Wireless] After modify wifi setting, all guest AP beacon will sent out. 11. [#137265][System] Sometimes WX3100 will hang and console can't print any information after SW reboot. (1/150 times) 12. [#139774][MPro Mesh] WX3100_AP Controller occurs call trace and the new wifi client cannot connect Controller wifi in ZyPark Mesh stress environment.

Modifications in 5.50(ABVL.0)b4

● Feature Enhancement

Modified Modules	Features Enhancement List
WLAN	1. ECONET update the max TX power <ul style="list-style-type: none"> ● mt7915d_max_tx_power_in_beacon_probe_rsp_test_patch

● Bug Fixed

Modified Modules	Bug Fixed List
WLAN	1. [PQA #137413] [MPro Mesh_Agent] Reboot Extender via APP fail 2. [PQA #137279] [MPro Mesh][1*AP_Agent + 2*RP_Agent topology] After AP controller do auto configure, RP_Agent occurs disconnect/reconnect continually and it does not sync wifi setting from AP Controller. 3. [PQA #135795] [MPro Mesh] AP roaming test fail 4. [PQA #135571] [MPro Mesh] Backhaul optimization cannot work. 5. [PQA #137451] [MPro Mesh_Agent] Modify Extender name will lead agent crash 6. [PQA #135735] [MPro Mesh] Wifi backhaul throughput test is poor 7. [PQA #135475] [Wireless] WX3100 disconnect and re-connect to gateway when clients connect to WX3100. 8. [PQA #135890] [MPro Mesh] ZyPark MPro stress test environment, Stress testing will cause "ZyMAPSteer" daemon disappear
SYSTEM	1. [PQA #137136] [TR-069] After reboot WX3100, ACS URL will change to default.

Modifications in 5.50(ABVL.0)b3

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
WLAN	<ol style="list-style-type: none"> [PQA #135385] [MPro Mesh] Controller table is empty in Steering status page. [PQA #135720] [MPro Mesh] It does not support L2Device reboot parameter in TR. [PQA #135386] [MPro Mesh] WX3100 does not support Mesh log category. [PQA #135377] [MPro Mesh] After do auto configure, sometimes RP_Agent cannot connect back AP controller. [PQA #135439] [MPro Mesh] Extender_RP will loop and it cannot connect back controller when do auto configure or controller do reboot/ FW upgrade/ restore backup configure file. [PQA #135115] [Wireless] SSID display error after run uplink/downlink WPS. [PQA #135571] [MPro Mesh] Backhaul optimization cannot work. [PQA #135795] [MPro Mesh] AP roaming test fail [PQA #135723] [MPro Mesh] Band steering, Wifi client information disappears, Returning to the controller will not steer wifi client to 5G. [PQA #135741] [MPro Mesh] It cannot dump 2nd layer agent in mesh station list by using "zyslctl -a". [PQA #135574] [MPro Mesh] Link quality led light green on RP controller even rssi less than -50. [PQA #135211] [Wireless] Link LED can't work on Repeater mode (Gateway disable MESH) [PQA #135772] [MPro Mesh] WX3100 Agent cannot sync controller wifi setting if SSID has space character.
SYSTEM	<ol style="list-style-type: none"> [PQA #135585] [MPro Mesh_Agent] APP cannot search

	<p>controller</p> <ol style="list-style-type: none"> [PQA #135236] [Stress]Overnight stress test, DUT will happen call trace [PQA #133469] [TR-069]After Modify ACS URL, reboot DUT will call trace [PQA #133578] [System] Call trace and hang problem after restore default, restore config or GUI reboot [PQA #133536] [System] WX3100 call trace after upgrade to dummy or b1 FW (Need reboot) [PQA #133654] [TR-069]Upgrade FW to dummy from ACS server, reboot process will call trace
LED	<ol style="list-style-type: none"> [PQA #135268] [LED] RP mode, When disconnect Gateway link, Link LED still on

Modifications in 5.50(ABVL.0)b2

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.50(ABVL.0)b1

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List