

ZYXEL Access Point

Release Note

Firmware V7.12 Patch 1

Date: October 19, 2026

Zyxel Access Points

V7.12(P1)C0 Release Note

Overview

This document provides firmware release information on Zyxel Access Points platforms, introduce new Access Points, new features and enhancements, bug fix, known issues and workarounds information for Release V7.12 Patch 1 C0.

Supported Platforms

- NWA110AX V7.12(ABTG.1)C0
- NWA210AX V7.12(ABTD.1)C0
- WAX510D V7.12(ABTF.1)C0
- WAX610D V7.12(ABTE.1)C0
- WAX630S V7.12(ABZD.1)C0
- WAX650S V7.12(ABRM.1)C0
- NWA50AX V7.12(ABYW.1)C0
- NWA55AXE V7.12(ABZL.1)C0
- NWA90AX V7.12(ACCV.1)C0
- NWA50AX PRO V7.12(ACGE.1)C0
- NWA55AX PRO V7.12(ACSP.1)C0
- NWA90AX PRO V7.12(ACGF.1)C0
- NWA55AX PTP V7.12(ACSQ.1)C0
- NWA220AX-6E V7.12(ACCO.1)C0
- WAX620D-6E V7.12(ACCN.1)C0
- WAX640S-6E V7.12(ACCM.1)C0
- WAX655E V7.12(ACDO.1)C0
- WAX300H V7.12(ACHF.1)C0

New Features and Enhancements

N/A

Bug fix

Bug Fix	Cloud	Managed	Standalone
1. [eITS: 260900563] [Symptom] disconnection logs may display an empty SSID value for Configuration Changed events.	V	-	-
2. [eITS: 260700412] [Symptom] Access Points may not properly disable or re-enable SSIDs as configured in the SSID schedule.	V	-	-
3. [Vulnerability] CVE-2026-6837 A command injection vulnerability may be present in the 'export-cgi' program after authentication.	V	V	V
4. [Vulnerability] CVE-2026-8508 An improper authentication vulnerability may exist in the 'social_login.cgi' program.	V	V	V

Known Issue

Known Issue	Cloud	Managed	Standalone
1. [eITS: 260800639] [Symptom] A clients may be unable to connect to a WPA3-Enterprise SSID when using a manually configured WPA3-Enterprise only wireless profile.	V	V	V
2. [eITS: 260800354] [Symptom] When an root AP (BE) and a repeater AP (AX) are connected via a 5G mesh link, wireless connections to the repeater AP may drop if the SSID is configured in bridge mode.	V	-	-
3. [RMID: 71121] [Symptom] On NWA55AX PTP devices, the PTP repeater LED may incorrectly indicate a WDS disconnected status even when the WDS connection is successfully established.	-	-	V
4. [eITS: 250401445] [Symptom] VLAN and Security fields in the clients list display incorrect values when 802.1x MAC authentication with VLAN assignment is used.	V		

Limitation of Settings:

N/A