

ZYXEL Access Point

Release Note

Firmware V7.40 Patch 2

Date: October 14, 2026

Zyxel Access Points

V7.40(P2)C0 Release Note

Overview

This document provides firmware release information on Zyxel Access Points platforms, introduce new Access Points, new features and enhancements, bug fix, known issues and workarounds information for Release V7.40 Patch 2 C0.

Supported Platforms

- NWA30BE V7.40(ACPI.2)C0
- NWA50BE V7.40(ACPB.2)C0
- NWA55BE V7.40(ACPH.2)C0
- NWA90BE V7.40(ACPD.2)C0
- NWA110BE V7.40(ACLZ.2)C0
- NWA130BE V7.40(ACIL.2)C0
- NWA210BE V7.40(ACLY.2)C0
- NWA240BE V7.40(ACQG.2)C0
- NWA50BE PRO V7.40(ACPC.2)C0
- NWA90BE PRO V7.40(ACPE.2)C0
- WBE510D V7.40(ACLX.2)C0
- WBE530 V7.40(ACLE.2)C0
- WBE630S V7.40(ACW.2)C0
- WBE660S V7.40(ACGG.2)C0
- WBE665S V7.40(ACQJ.2)C0
- NWA210AXv2 V7.40(ACSR.2)C0
- IAP500BE V7.40(ACPJ.2)C0
- Root Plus V7.40(ACQK.2)C0
- Leaf Plus V7.40(ACQL.2)C0
- Root V7.40(ACUJ.2)C0

New Features and Enhancements

N/A

Bug fix

Bug Fix	Cloud	Managed	Standalone
1. [eITS: 260401951] [Symptom] Devices may intermittently switch between APs.	V	V	V
2. [eITS: 260402280] [Symptom] iPhone devices may experience repeated Wi-Fi reconnection behavior.	V	V	V
3. [eITS: 250601699] [Symptom] The AP may experience abnormal time display.	V	V	V
4. [eITS: 260700412] [Symptom] The SSID schedule may fail to apply on APs.	V	-	-
5. [eITS: 260701083] [Symptom] The AP may remain in 'Not Up-to-Date' configuration status even after its configuration has been changed.	V	-	-
6. [eITS: 260801409] [Symptom] Intermittent 2.4GHz connectivity issues may occur on meshed APs.	V	V	V

7. [eITS: 260801763] [Symptom] NTP synchronization may fail on APs.	V	-	-
8. [eITS: 260901264] [Symptom] iPhone fails to connect to a WPA3-secured SSID.	V	V	V
9. [eITS: 260901934] [Symptom] The AP LAN port becomes enabled after a reboot, even though it was disabled in Nebula.	V	-	-
10. [eITS: 260600285] [Symptom] Wi-Fi 5 clients experience intermittent connectivity issues.	V	V	V
11. [eITS: 260402066] [Symptom] The AP does not reboot according to the configured daily reboot schedule.	V	-	-
12. [SPRID: 71853] [Symptom] Sensitive data may be included in diagnostic information.	V	V	V
13. [SPRID: 71538] [Symptom] A pre-authentication buffer overflow vulnerability may exist in the zdp_wtp component of AP.	V	V	V
14. [Vulnerability] CVE-2026-6837 A post-authentication command injection vulnerability in the "export-cgi" CGI program.	V	V	V

15. [Vulnerability] CVE-2026-8508 An improper authentication vulnerability in the "social_login.cgi" CGI program.	V	V	V
---	---	---	---

Known Issue

Known Issue	Cloud	Managed	Standalone
1. [eITS: 260900184] [Symptom] Enable AP Group and tagging SSID will cause AP hang.	V	-	-
2. [eITS: 260900184] [Symptom] some WPA3-Enterprise clients may fail to connect.	V	V	V

Limitation of Settings:

N/A