

## **Zyxel Firmware Release Note**

**Model Name: WAP3205 v3**

**Release Version: V2.00(ABDM.5)C0**

**Release Date: Mar 1 , 2022**

### **Product information**

- Default LAN IP: 192.168.1.2
- Default username: admin
- Default password: 1234
- The WAP3205 v3 is set as AP mode by default, if users choose a different mode, such as Universal Repeater mode or Client bridge mode, the system will be reboot before the settings.
- Firmware upgrades may reset the AP's configuration options to the factory if you select "Automatically reset default after firmware upgraded". Before performing an upgrade, please backup you current configuration first.

### **Known Issues**

1. WPS button works only for downlink connection in AP mode and Repeater mode.
2. There is an IOP issue with Ralink3352 AP (Router)
3. Sometimes the DHCP client table only show LAN port client

### **Modification in V2.00(ABDM.5)C0 | Mar/1/2022**

1. Fix issue for dhcp about lease time in client bridge mode.
2. Add power size message in web
3. Support '\ ' character in wireless password
4. Fix issue for LAN IP in MacOS 10.13.6 version

### **Modification in V2.00(ABDM.4)C0 | May/15/2018**

1. Fix: In Repeater mode, after power off and on WAP3205 v3 won't reconnect back to router.

**Modification in V2.00(ABDM.3)C0 | Dec/26/2017**

1. Fix WPA2 KRACK vulnerability, official release

**Modification in V2.00(ABDM.2)C0\_20171114 | Nov/24/2017**

1. Fix WPA2 KRACK vulnerability, hot fix

**Modification in V2.00(ABDM.2)C0 | April/07/2017**

1. Firmware upgrade support Firefox

**Modification in V2.00(ABDM.1)C0 | January/13/2017**

1. Fix the "AP will send IPv6 DHCP gateway IP" issue
2. Support LAN IP to class B

**Modification in V2.00(ABDM.0)C0 | October /05/2016**

1. Support Universal Repeater mode and Client bridge mode settings in the Wizard
2. Remove Time zone
3. Fix WPS PIN code issue

**Modification in V1.00(ABDM.1)C0 | April/29/2016**

First Release