

Zyxel

Firmware Release Note

WSR30

Release V1.00(ABMY.13)C0

WSR30
Release V1.00(ABMY.13)C0
Release Notes

Date: July 1, 2022

Supported Platforms:

Zyxel WSR30

Release Package:

File name	
V1.00(ABMY.13)C0.bin	WSR30 Firmware Package for standard version
V1.00(ABMY.13)C0.pdf	Firmware release note

Features:

Enhancement in V1.00(ABMY.13)C0 | 07/01/2022

[Enhancement]

1. Upgrade Cloud root CA.
2. Add external guest WiFi of WAN client block LAN network.
3. Support TFTP client on LAN side can download data from TFTP server on WAN side.

Enhancement in V1.00(ABMY.12)C0 | 10/25/2021

[Enhancement]

1. Update DUT's root password process for root access of the device.
2. Add debug firmware upgrade page and remove SSH remote.

[Bug Fix]

1. Schedule cannot block streaming type immediately.
 2. Fix speed test get stuck in the upload.
 3. Wired connected node will disconnected from Root.
 4. Fix DeAgg and DeFrag Attack.
 5. Fix cloud agent curl callback function return size error.
 6. Update ca-certificates version to 20200119.
-

Enhancement in V1.00(ABMY.12)C0 | 10/25/2021

[Enhancement]

1. Update DUT's root password process for root access of the device.
2. Add debug firmware upgrade page and remove SSH remote.

[Bug Fix]

1. Schedule cannot block streaming type immediately.
2. Fix speed test get stuck in the upload.
3. Wired connected node will disconnected from Root.
4. Fix DeAgg and DeFrag Attack.
5. Fix cloud agent curl callback function return size error.
6. Update ca-certificates version to 20200119.

Enhancement in V1.00(ABMY.11)C0 | 08/20/2020

[Bug Fix]

1. Diagnose > Speed Test > Tap Test, then get stuck in the upload

Enhancement in V1.00(ABMY.11)C0 | 08/20/2020

[Bug Fix]

1. Diagnose > Speed Test > Tap Test, then get stuck in the upload

Enhancement in V1.00(ABMY.10)C0 | 03/12/2020

[Enhancement]

1. Apply ppp-2.4.7 security vulnerability issue.

[Bug Fixed]

1. Fix client cannot access internet through guest Wi-Fi network in bridge mode.

Enhancement in V1.00(ABMY.9)C0 | 12/23/2019

[Enhancement]

1. Enhance tri-band AP when only one device installed.
2. Enhance abnormal issue cause system unstable.

Enhancement in V1.00(ABMY.8)C0 | 10/7/2019

[Enhancement]

1. AP steering mechanism improve for sometimes client does not roam to DUT
-

properly.

2. LED behavior update when WiFi 5G low band disconnected in EU version.

[Bug Fixed]

1. Fix sometimes firmware upgrade finished but not reboot issue

Enhancement in V1.00(ABMY.7)C0 | 7/29/2019

[Bug Fixed]

1. Fix IOS minecraft gaming app login procedure takes long time.

2. Fix sometime diagnose WiFi Signal check function cannot work.

Enhancement in V1.00(ABMY.6)C0 | 5/31/2019

[Enhancement] Enhance LED dimming via LED button.

Enhancement in V1.00(ABMY.5)C0 | 3/15/2019

[Enhancement] Enhance DFS mechanism.

Enhancement in V1.00(ABMY.1)C0 | 9/13/2018

[Initial Version]
