

Zyxel

Firmware Release Note

WSM20

Release V1.00(ABZF.6)C0

WSM20 Release V1.00(ABZF.6)C0

Release Notes

Date: October 23, 2023

Supported Platforms:

Zyxel WSM20

Release Package:

File name	
V1.00(ABZF.6)C0.bin	WSM20 Firmware Package for standard version
V1.00(ABZF.6)C0.pdf	Firmware release note

Features:

Enhancement in V1.00(ABZF.6)C0 | 10/23/2023

Enhancement:

1. Modify uMeshSteer monitor. Make it more stable.

Bug Fixed:

1. Fix in dual stack mode, LINE cannot be used normally with IPV6.
2. Adding time out to fix DNS server connection failure in Multy APP.
3. Fix Traffic Separation vlan tag error.
4. Fix webgui keep loading on parental control.

Features:

Enhancement in V1.00(ABZF.5)C0 | 07/03/2022

Enhancement:

1. Modify agent online check & fix update bssid.
 2. support "Digitalisierungsbox PREMIUM 2" and "Digitalisierungsbox SMART 2" follow uMeshController db.
 3. Add patch to remove mtk mesh send arping.
 4. Add HLD to send reload mesh req.
-

Bug Fixed:

1. Fix uMeshController daemon failed.
2. Fix Write /tmp/ApplicationData/map.cfg failed.
3. When set traffic_separation data, to check old value.
4. If controller mesh daemon failed, send request to reload agent mesh.
5. When change backhaul type [Ethernet->WiFi], send request to reload agent mesh.

Enhancement in V1.00(ABZF.4)C0 | 05/12/2022

Enhancement:

1. Support Mesh uplink information
2. Support External Guest function
3. OpenSSL vulnerability update 1.1.1n patch

Bug Fixed:

1. Remove UPnP Network device detail information with serial number
2. Force FW upgrade tap cancel direct to wrong page

Enhancement in V1.00(ABZF.3)C0 | 03/31/2022

Enhancement:

1. Support IGMPv3

Enhancement in V1.00(ABZF.2)C0 | 02/21/2022

Bug Fixed:

1. Fix Power LED and Wireless LED non reason blinking.
 2. Change System Name and Domain Name, agent LED is blinking and cannot connect controller.
 3. Change WiFi setting and agent sometimes cannot connect to controller.
 4. After Agent associate to Controller via WPS, Agent reboot without log
 5. DUAL Stack+IPv6 LAN End number less than Start number "Apply" should not be accepted
 6. Use GUI install M1 then Multy Android APP open IPv6 that LAN address will repeat
 7. Parental Control add same profile name and fail to change profile
 8. APP can not delete "off-line" client from client list
-

9. If Agent uplink is down, then Agent LED is not blinking for WPS downlink process

Enhancement in V1.00(ABZF.1)C0 | 11/15/2021

1. Update DUT's root password process for root access of the device.
2. Add debug firmware upgrade page and remove SSH remote.

Bug Fixed:

1. Notifications cannot work fine.
2. In Diagnose/Mesh page, Multy name should show user-defined name
3. Home > Multy Router > enable IPv6, then IPv6 page not display WAN IP and LAN IP
4. Install as stand alone, the wireless clients not show in Parental control page
5. If Controller is in bridge mode. then Agent not show detail information in GUI
6. After Device reboot, New client notification will inform to APP again.

Enhancement in V1.00(ABZF.0)C0 | 08/31/2021

[Initial Version]
