

GM4100-B0

Firmware Release Note

V5.18(ACCL. 2)C0

Date: January 9, 2026

Author: Stanley Chung

Reviewer: Howard

THIS DOCUMENT CONTAINS PROPRIETARY TECHNICAL INFORMATION THAT IS THE PROPERTY OF THE Zyxel AND SHOULD NOT BE DISCLOSED TO OTHERS IN WHOLE OR IN PART, REPRODUCED, COPIED, OR USED AS BASIS FOR DESIGN, MANUFACTURING OR SALE OF APPARATUS WITHOUT WRITTEN PERMISSION OF Zyxel.

TABLE OF CONTENTS

REVISION HISTORY.....	4
SUPPORTED PLATFORMS:.....	5
VERSIONS:	5
NOTES:.....	5
PUBLIC DOMAIN SOFTWARE ANNOUNCEMENTS	6
KNOWN ISSUES.....	9
MODIFICATIONS IN 5.18(ACCL.2)C0	9
MODIFICATIONS IN 5.18(ACCL.2)B4	9
MODIFICATIONS IN 5.18(ACCL.2)B3	10
MODIFICATIONS IN 5.18(ACCL.2)B2	10
MODIFICATIONS IN 5.18(ACCL.2)B1	11
MODIFICATIONS IN 5.18(ACCL.1)C0	11
MODIFICATIONS IN 5.18(ACCL.1)B5	11
MODIFICATIONS IN 5.18(ACCL.1)B4	12
MODIFICATIONS IN 5.18(ACCL.1)B3	12
MODIFICATIONS IN 5.18(ACCL.1)B2	13
MODIFICATIONS IN 5.18(ACCL.1)B1	13
MODIFICATIONS IN 5.18(ACCL.0)C0	13
MODIFICATIONS IN 5.18(ACCL.0)B9	14
MODIFICATIONS IN 5.18(ACCL.0)B8	14
MODIFICATIONS IN 5.18(ACCL.0)B7	15
MODIFICATIONS IN 5.18(ACCL.0)B6_D0	15
MODIFICATIONS IN 5.18(ACCL.0)B6	16
MODIFICATIONS IN 5.18(ACCL.0)B5_D0	16
MODIFICATIONS IN 5.18(ACCL.0)B5	17
MODIFICATIONS IN 5.18(ACCL.0)B4	17

MODIFICATIONS IN 5.18(ACCL.0)B3 18

MODIFICATIONS IN 5.18(ACCL.0)B2 18

MODIFICATIONS IN 5.18(ACCL.0)B1 19

Revision History

Date	Release	Author	Description
2021/12/07	1.0	CHI-HAO	FW release for V5.18(ACCL.0)b1
2022/02/11	2.0	CHI-HAO	FW release for V5.18(ACCL.0)b2
2022/05/11	2.1	CHI-HAO	FW release for V5.18(ACCL.0)b3
2022/08/05	2.2	CHI-HAO	FW release for V5.18(ACCL.0)b4
2022/12/02	2.3	Stanley Chung	Release for V5.18(ACCL.0)b5
2022/12/02	2.4	Stanley Chung	Release for V5.18(ACCL.0)b5_D0 (Ext Ver: V5.19.b)
2023/02/10	2.5	Stanley Chung	Release for V5.18(ACCL.0)b6
2023/02/10	2.6	Stanley Chung	Release for V5.18(ACCL.0)b6_D0 (Ext Ver: V5.27)
2023/03/24	2.7	Stanley Chung	Release for V5.18(ACCL.0)b7
2023/06/19	2.8	Stanley Chung	Release for V5.18(ACCL.0)b8
2024/03/15	2.9	Stanley Chung	Release for V5.18(ACCL.0)b9
2024/04/03	3.0	Stanley Chung	Release for V5.18(ACCL.0)C0
2024/04/29	3.1	Stanley Chung	Release for V5.18(ACCL.1)b1
2024/05/17	3.2	Stanley Chung	Release for V5.18(ACCL.1)b2
2024/06/21	3.3	Stanley Chung	Release for V5.18(ACCL.1)b3
2024/08/09	3.4	Stanley Chung	Release for V5.18(ACCL.1)b4
2025/05/26	3.5	Stanley Chung	Release for V5.18(ACCL.1)b5
2025/06/12	3.6	Stanley Chung	Release for V5.18(ACCL.1)C0
2025/09/19	3.7	Stanley Chung	Release for V5.18(ACCL.2)b1
2025/09/25	3.8	Stanley Chung	Release for V5.18(ACCL.2)b2
2025/11/04	3.9	Stanley Chung	Release for V5.18(ACCL.2)b3
2025/12/17	4.0	Stanley Chung	Release for V5.18(ACCL.2)b4
2025/01/09	4.1	Stanley Chung	Release for V5.18(ACCL.2)C0

**GM4100-B0
V5.18(ACCL.2)C0
Release Note**

Date: January 09, 2025

Supported Platforms:

Zyxel GM4100-B0

Versions:

Bootbase version : V2.1

Firmware version : V5.18(ACCL.2)C0

Kernel version : 4.19.183

DSL modem code version: ApvfbM49c

DSL driver version: 28h

Notes:

Public Domain Software Announcements

Open Source Used In Product	Version	From (Source)	License Terms	Modified / Used
attr	2.5.1	http://savannah.nongnu.org/projects/attr	GPLv2	Used
atftp	0.7.4	https://sourceforge.net/projects/atftp/	GPLv2	Modified
bridge-Utils	1.7.1	https://git.kernel.org/pub/scm/linux/kernel/git/shemminger/bridge-utils.git/	GPLv2	Modified
busybox	1.31.1	https://busybox.net/	GPLv2	Modified
clinkc	2.4	https://sourceforge.net/projects/clinkc/	BSD	Modified
conntrack-tools	1.4.5	https://git.netfilter.org/conntrack-tools/	GPLv2	Used
dnsmasq	2.85	http://www.thekelleys.org.uk/dnsmasq/doc.html	GPLv2/GPLv3	Modified
dropbear	2019.78	https://github.com/mkj/dropbear	MIT	Modified
ebtables	018-06-27-48c ff25d	https://git.netfilter.org/ebtables/	GPLv2	Modified
eventlog	0.2.10	https://github.com/balabit/eventlog	BSD	Used
expat	2.7.1	https://github.com/libexpat/libexpat	MIT	Used
ez-ipupdate	3.0.11b8	http://ez-ipupdate.com/	GPLv2	Modified
gettext	0.19.8.1	http://www.gnu.org/software/gettext/	GPLv3	Used
glib	2.68.1	http://www.gtk.org/	LGPLv2.1	Used
iproute2	5.7.0	https://github.com/shemminger/iproute2	GPLv2	Modified
iptables	1.8.5	https://git.netfilter.org/iptables/	GPLv2	Modified
jpegsrsrc	v9c	http://www.iijg.org/	IJG	Used
json-c	0.13.1	https://github.com/json-c/json-c/downloads	MIT	Modified
libedit	20080712-2.11	http://pkgs.fedoraproject.org/repo/pkgs/libedit/libedit-20080712-2.11.tar.gz/	BSD	Modified
libffi	3.3	http://pkgs.fedoraproject.org/repo/pkgs/libffi/libffi-3.0.11.tar.gz/	MIT	Used
libiconv	1.11.1	http://www.gnu.org/software/libiconv/	LGPLv2	Modified
libnetfilter_conntrack	1.0.7	https://git.netfilter.org/libnetfilter_conntrack/	GPLv2	Used
libnetfilter_queue	1.0.3	https://git.netfilter.org/libnetfilter_queue/	GPLv2	Used

eue				
libnfnetwork	1.0.1	https://git.netfilter.org/libnfnetwork/	GPLv2	Used
libnl-tiny	0.1	https://github.com/openwrt/openwrt/tree/master/package/libs/libnl-tiny	GPLv2/LGPLv2.1	Used
libpcap	1.9.1	www.tcpdump.org	BSD	Used
libtool	2.4.6	http://www.gnu.org/software/libtool/	GPLv2	Used
libusb	1.0.9	https://sourceforge.net/projects/libusb/	LGPL 2.1	Used
Linux/Arm Kernel	4.19.183		GPLv2	Modified
logrotate	3.7.1	https://launchpad.net/ubuntu/hardy/i386/logrotate/	GPLv2	Modified
mailsend	1.17b15	https://github.com/muquit/mailsend/	BSD	Modified
ncurses	6.1	http://ftp.gnu.org/pub/gnu/ncurses/	MIT	Modified
net-snmp	5.8	http://www.net-snmp.org/	ISC/BSD	Modified
ntfs-3g	2017.3.23-2	http://ntfs-3g.org	GPLv2/LGPLv2	Used
ntpclient	2007_365	http://doolittle.icarus.com/ntpclient/	GPLv2	Modified
openssl	1.1.1f	http://www.openssl.org	OpenSSL	Modified
popt	1.16	http://rpm5.org/files/popt/	MIT	Modified
ppp	2.4.3	http://www.roaringpenguin.com/pppoe	GPLv2/BSD	Modified
pure-ftpd	1.0.30	http://pureftpd.org	ISC/BSD	Modified
radvd	1.8	http://www.litech.org/radvd/	BSD	Used
readline	8.0	http://cnswww.cns.cwru.edu/php/chet/readline/rltop.html	GPLv2	Used
samba	3.0.37	http://www.samba.org/samba/	GPLv3	Modified
sqlite	3.31.0	http://www.sqlite.org/	Public Domain License	Used
syslog-ng	2.0.10	https://github.com/balabit/syslog-ng	GPLv2	Used
tcpdump	4.9.3	http://www.tcpdump.org/	BSD	Used
udhcp	0.9.8	http://udhcp.busybox.net/	GPLv2	Modified
usb-modeswitch	2.1.0	http://www.draisberghof.de/usb_modeswitch/	GPLv2	Used
util-linux	2.34	https://github.com/karelzak/util-linux/	GPLv2	Used
wide-dhcpv6	20080615	https://sourceforge.net/projects/wide-dhcpv6/	BSD	Modified
zebra	0.93a	http://www.zebra.org/	GPLv2/LGPLv2	Used

zlib	1.2.11	https://github.com/madler/zlib	zlib	Used
------	--------	---	------	------

Known issues

Modules	Issue	Risk Impact Information

Modifications in 5.18(ACCL.2)C0

- Feature Enhancement

Modified Modules	Features Enhancement List
	Based on v5.18(ACCL.2)b4 to release v5.18(ACCL.2)C0

- Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.18(ACCL.2)b4

- Feature Enhancement

Modified Modules	Features Enhancement List
Vulnerability	[Zyxel-SI-1644][Vulnerability] Command injection vulnerabilities in zupnp and zhttpd binaries in customized firmware of the EX3301-T0

- Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.18(ACCL.2)b3

- Feature Enhancement

Modified Modules	Features Enhancement List

- Bug Fixed

Modified Modules	Bug Fixed List
Vulnerability	[Zyxel-SI-1638][Vulnerability] Multiple potential null pointer dereference vulnerabilities in the CGI program
Vulnerability	[CVE-2025-6599] Zyxel-SI-1616 [Vulnerability] Slow HTTP DoS vulnerability in the DX3301-T0
Vulnerability	[CVE-2025-6599] Zyxel-SI-1621 [Vulnerability] Slow read DoS vulnerability on the zhttpd web server
Vulnerability	[CVE-2025-8693] Zyxel-SI-1624 [Vulnerability] A post-authentication command injection vulnerability in the certificate upload CGI program of DX3300-T0 and VMG3925-B10B

Modifications in 5.18(ACCL.2)b2

- Feature Enhancement

Modified Modules	Features Enhancement List
xDSL	Upgrade modem code and DSL driver to ApvfbM49c.28h

- Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.18(ACCL.2)b1

- Feature Enhancement

Modified Modules	Features Enhancement List
System	Release FW for H0/F0

- Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.18(ACCL.1)C0

- Feature Enhancement

Modified Modules	Features Enhancement List
	Based on v5.18(ACCL.1)b5 to release v5.18(ACCL.1)C0

- Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.18(ACCL.1)b5

- Feature Enhancement

Modified Modules	Features Enhancement List
WEB	WEB GUI meets the request of Europe EAA (European Accessibility Act)

- Bug Fixed

Modified Modules	Bug Fixed List

EXPAT	Zyxel-SI-1605 [Vulnerability] The libexpat open source library is vulnerable to DoS attacks through stack overflow
DST	[System] Follow DST, TR-069 "Validate ACS certificate" should be enabled by default.
WAN	[WAN] CPE WAN can not get IPv6 address because of there is no IANA and IAPD in Solicit packet
WAN	[WAN] CPE and LAN Client can not get IP address when CPE linkup with ADSL
DST	[System] The DST file and GUI are not match to each other

Modifications in 5.18(ACCL.1)b4

- Feature Enhancement

Modified Modules	Features Enhancement List
WEB	[eITS#240701511] Quick Start Wizard works not correct GM4100-B0

- Bug Fixed

Modified Modules	Bug Fixed List
Security	[CVE-2024-38266, 38267, 38268, 38269][Zyxel-SI-1559] Multiple authenticated buffer overflow vulnerabilities

Modifications in 5.18(ACCL.1)b3

- Feature Enhancement

Modified Modules	Features Enhancement List

- Bug Fixed

Modified Modules	Bug Fixed List
Vulnerability	[eITS#240600627][A1][Mantis-7312] Vulnerability - Zyxel SI-1557

Vulnerability	[eITS#240600626][A1][Mantis-7311] Vulnerability - Zyxel SI-1559
---------------	---

Modifications in 5.18(ACCL.1)b2

- Feature Enhancement

Modified Modules	Features Enhancement List
WAN	Support multiple DSL phy binary file in system

- Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.18(ACCL.1)b1

- Feature Enhancement

Modified Modules	Features Enhancement List
WAN	[eITS#230901184][DT] Synch values are too low on some modems in the 48 cable

- Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.18(ACCL.0)C0

- Feature Enhancement

Modified	Features Enhancement List
----------	---------------------------

Modules	
	Based on v5.18(ACCL.0)b9 to release v5.18(ACCL.0)C0

- Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.18(ACCL.0)b9

- Feature Enhancement

Modified Modules	Features Enhancement List
WEB	[eITS#231001973] translation in Germany

- Bug Fixed

Modified Modules	Bug Fixed List
System	[System] In CLI mode, lack Product Model information after key in "sys atsh"
LAN	[eITS#230301803] Test Bridge works no longer GM 4100-B0
WEB	[eITS#231001083] on basic overview page the device is showing "interrupted connection" though VDSLsync is actually present
TR069	[eITS#240200035] TR69 ACS URL option43 will trigger Firmware update GM4100-B0
Security	[Vulnerability][Zyxel-SI-1536] Buffer overflow vulnerability in the "traceroute"

Modifications in 5.18(ACCL.0)b8

- Feature Enhancement

Modified	Features Enhancement List
----------	---------------------------

Modules	

- Bug Fixed

Modified Modules	Bug Fixed List
	[Vulnerability] OpenSSL multiple vulnerabilities

Modifications in 5.18(ACCL.0)b7

- Feature Enhancement

Modified Modules	Features Enhancement List
Zloader	Add password keys recovery mechanism to avoid system operation issues when upgrading older FW(before 0b4) to a new one.

- Bug Fixed

Modified Modules	Bug Fixed List
DSL Drivers	Modify the DSL driver and have the DSL software version could be shown on DSLAM properly. Version should be "ApvfbM48c.27n 14".

Modifications in 5.18(ACCL.0)b6_D0

- Bug Fixed/ Feature Enhancement

Modified Modules	Bug Fixed List
Security	Disable the DNS port53 when services are not enabled
FW Upgrade	[DSL][System] Support the ACTIVE message command (56h) for G9701.Annex.S NT FW management function. With this

	command, CPE is going to switch the image partition when receiving the request.
--	---

Modifications in 5.18(ACCL.0)b6

- Bug Fixed

Modified Modules	Bug Fixed List
DSL Drivers	Following the customer's request to update the DSL software version format from "A2pvfbM048c.d27n" to "ApvfbM48c.27n14".
WEB	Follow the specification to hide IGMP/MLD page in Network setting from WEB

Modifications in 5.18(ACCL.0)b5_D0

- New Feature

New Modules	Features Enhancement List
FW Upgrade	[DSL][System] Support G9701.Annex.S NT FW Management to allow firmware upgrade through DSLAM/DPU.

- Bug Fixed

Modified Modules	Bug Fixed List
Security	Zyxel-SI-1433 [Vulnerability] Buffer overflow vulnerabilities and command injection vulnerability for GM4100
	Unsafe User-Controlled Configuration Data (SMB) (High: 27) for GM4100
	Unsafe Symbolic Link Processing (SMB) for GM410
WEB	[Account]: Following TPG request to support customized Account and Password
	[IP]: Following TPG request to update default IP, Netmask and

	listen port
	[WEB]: Remove management services except https and SSH
	[WEB]: Menu list support "Connection Status", "System Monitor" and "Maintenance".
	[WEB]: System Monitor only support "Log", "Traffic Status", and "xDSL Statics" page
	[WEB]: Maintenance support "System", "User Account", "remote Management", "Log Setting", and "Reboot"
	[WEB]: Account of "vision_zyxel" can access the hidden page of portmirro

Modifications in 5.18(ACCL.0)b5

- New Feature

Modified Modules	Features Enhancement List
FW Upgrade	[DSL][System] Support G9701.Annex.S NT FW Management to allow firmware upgrade through DSLAM/DPU.

- Bug Fixed

Modified Modules	Bug Fixed List
Security	Zyxel-SI-1433 [Vulnerability] Buffer overflow vulnerabilities and command injection vulnerability for GM4100
	Unsafe User-Controlled Configuration Data (SMB) (High: 27) for GM4100
	Unsafe Symbolic Link Processing (SMB) for GM410

Modifications in 5.18(ACCL.0)b4

- Feature Enhancement

Modified Modules	Features Enhancement List

- Bug Fixed

Modified Modules	Bug Fixed List
Security	
Wan	[WAN] Follow OPAL_Generic, CPE should support source of multiple IPv6 address in WAN informa
Management	[Management] CPE should also enable CWMP and set Inform Interval via Option43
	[Management] CPE should base on the WAN Mode to display the WAN in Multi-WAN options
	[Management] DeviceSummary should not list the function that CPE not support
	[Management] The Category in System Monitor \ Log page with IGMP option
System	[System] There is no WAN Name in System Info page
MAC	[GM4100-B0] GUI can't login issue duplicate
	[Internal] sys atwz MAC length issue

Modifications in 5.18(ACCL.0)b3

- Feature Enhancement

Modified Modules	Features Enhancement List

- Bug Fixed

Modified Modules	Bug Fixed List
Security	[Vulnerability] Infinite loop in BN_mod_sqrt() of OpenSSL when parsing certificates
	[Zyxel-SI-1377] cleartext storage of sensitive information vulnerability

Modifications in 5.18(ACCL.0)b2

- Feature Enhancement

Modified Modules	Features Enhancement List

- **Bug Fixed**

Modified Modules	Bug Fixed List

Modifications in 5.18(ACCL.0)b1

- **Feature Enhancement**

Modified Modules	Features Enhancement List

- **Bug Fixed**

Modified Modules	Bug Fixed List