

PM7300-T0 Generic

Firmware Release Note

V5.42(ABYY.4.1)C0

Date: Dec. 30, 2025

Author: Justin Lin

Reviewer:

THIS DOCUMENT CONTAINS PROPRIETARY TECHNICAL INFORMATION THAT IS THE PROPERTY OF THE Zyxel AND SHOULD NOT BE DISCLOSED TO OTHERS IN WHOLE OR IN PART, REPRODUCED, COPIED, OR USED AS BASIS FOR DESIGN, MANUFACTURING OR SALE OF APPARATUS WITHOUT WRITTEN PERMISSION OF Zyxel.

TABLE OF CONTENTS

REVISION HISTORY.....	4
SUPPORTED PLATFORMS:.....	6
VERSIONS:	6
NOTES:.....	6
MODIFICATIONS IN V5.42(ABYY.4.1)C0	9
MODIFICATIONS IN V5.42(ABYY.4.1)B1	9
MODIFICATIONS IN V5.42(ABYY.4)C0	9
MODIFICATIONS IN V5.42(ABYY.4)B2	9
MODIFICATIONS IN V5.42(ABYY.4)B1	10
MODIFICATIONS IN V5.42(ABYY.3)C0	10
MODIFICATIONS IN V5.42(ABYY.3)B1	11
MODIFICATIONS IN V5.42(ABYY.2.3)C0	11
MODIFICATIONS IN V5.42(ABYY.2.3)B1	11
MODIFICATIONS IN V5.42(ABYY.2.2)C0	11
MODIFICATIONS IN V5.42(ABYY.2.2)B1	12
MODIFICATIONS IN V5.42(ABYY.2.1)C0	12
MODIFICATIONS IN V5.42(ABYY.2.1)B1	12
MODIFICATIONS IN V5.42(ABYY.2)C0	12
MODIFICATIONS IN V5.42(ABYY.2)B3	12
MODIFICATIONS IN V5.42(ABYY.2)B2	13
MODIFICATIONS IN V5.42(ABYY.2)B1	13
MODIFICATIONS IN V5.42(ABYY.1.3)C0	14
MODIFICATIONS IN V5.42(ABYY.1.3)B1	14
MODIFICATIONS IN V5.42(ABYY.1.2)C0	15
MODIFICATIONS IN V5.42(ABYY.1.2)B1	15
MODIFICATIONS IN V5.42(ABYY.1.1)C0	15

MODIFICATIONS IN V5.42(ABYY.1.1)B1	15
MODIFICATIONS IN V5.42(ABYY.1)C0	16
MODIFICATIONS IN V5.42(ABYY.1)B2	16
MODIFICATIONS IN V5.42(ABYY.1)B1	16
MODIFICATIONS IN V5.42(ABYY.0)C0	17
MODIFICATIONS IN V5.42(ABYY.0)B8	17
MODIFICATIONS IN V5.42(ABYY.0)B7	18
MODIFICATIONS IN V5.42(ABYY.0)B6	18
MODIFICATIONS IN V5.42(ABYY.0)B5	19
MODIFICATIONS IN V5.42(ABYY.0)B4	20
MODIFICATIONS IN V5.42(ABYY.0)B3	21
MODIFICATIONS IN V5.42(ABYY.0)B2	22
MODIFICATIONS IN V5.42(ABYY.0)B1	23

Revision History

Date	Release	Author	Description
2021/03/19	1.0	GuanHong Chen	FW release for V5.42(ABYY.0)b1
2021/04/23	2.0	GuanHong Chen	FW release for V5.42(ABYY.0)b2
2021/07/09	3.0	GuanHong Chen	FW release for V5.42(ABYY.0)b3
2021/08/13	4.0	GuanHong Chen	FW release for V5.42(ABYY.0)b4
2021/09/17	5.0	GuanHong Chen	FW release for V5.42(ABYY.0)b5
2021/10/14	6.0	GuanHong Chen	FW release for V5.42(ABYY.0)b6
2021/11/11	7.0	GuanHong Chen	FW release for V5.42(ABYY.0)b7
2021/11/21	8.0	GuanHong Chen	FW release for V5.42(ABYY.0)b8
2022/07/14	9.0	ChihJia Lee	FW release for V5.42(ABYY.1)b1
2022/11/24	10.0	Cindy Chen	FW release for V5.42(ABYY.1)b2
2022/12/02	11.0	Cindy Chen	FW release for V5.42(ABYY.1)C0
2023/04/12	12.0	Cindy Chen	FW release for V5.42(ABYY.1.1)b1
2023/04/17	13.0	Cindy Chen	FW release for V5.42(ABYY.1.1)C0
2023/06/09	14.0	Cindy Chen	FW release for V5.42(ABYY.1.2)b1
2023/06/12	15.0	Cindy Chen	FW release for V5.42(ABYY.1.2)C0
2023/07/25	16.0	Cindy Chen	FW release for V5.42(ABYY.1.3)b1
2023/08/04	17.0	Cindy Chen	FW release for V5.42(ABYY.1.3)C0
2023/09/07	18.0	Cindy Chen	FW release for V5.42(ABYY.2)b1

2023/10/31	19.0	Zhongde Lai	FW release for V5.42(ABYY.2)b2
2023/12/08	20.0	Cindy Chen	FW release for V5.42(ABYY.2)b3
2023/12/18	21.0	Cindy Chen	FW release for V5.42(ABYY.2)C0
2024/03/22	22.0	Cindy Chen	FW release for V5.42(ABYY.2.1)b1
2024/03/26	23.0	Cindy Chen	FW release for V5.42(ABYY.2.1)C0
2024/06/27	24.0	Cindy Chen	FW release for V5.42(ABYY.2.2)b1
2024/06/27	25.0	Cindy Chen	FW release for V5.42(ABYY.2.2)C0
2024/10/16	26.0	Cindy Chen	FW release for V5.42(ABYY.2.3)b1
2024/10/16	27.0	Cindy Chen	FW release for V5.42(ABYY.2.3)C0
2025/01/14	28.0	Cindy Chen	FW release for V5.42(ABYY.3)b1
2025/01/15	29.0	Cindy Chen	FW release for V5.42(ABYY.3)C0
2025/05/23	30.0	Cindy Chen	FW release for V5.42(ABYY.4)b1
2025/09/04	31.0	Cindy Chen	FW release for V5.42(ABYY.4)b2
2025/09/12	32.0	Cindy Chen	FW release for V5.42(ABYY.4)C0
2025/12/30	33.0	Justin Lin	FW release for V5.42(ABYY.4.1)b1
2025/12/30	34.0	Justin Lin	FW release for V5.42(ABYY.4.1)C0

PM7300-T0 Generic V5.42(ABYY.4.1)C0 Release Note

Date: Dec. 30, 2025

Supported Platforms:

Zyxel PM7300-T0

Versions:

Bootbase Version : V1.44 | 09/07/2023 15:30:09

Firmware version : V5.42(ABYY.4.1)C0

Kernel version: 4.4.115

Notes:

Public Domain Software Announcements

Open Source Used In Product	Version	From (Source)	License Terms	Modified / Used
atftp	0.8.0	https://sourceforge.net/projects/atftp/	GPLv2	Modified
bridge-Utills	1.5	https://git.kernel.org/pub/scm/linux/kernel/git/shemminger/bridge-utils.git/	GPLv2	Modified
busybox	1.20.1	https://busybox.net/	GPLv2	Modified
clinkc	2.4	https://sourceforge.net/projects/clinkc/	BSD	Modified
conntrack-tools	1.4.3	https://git.netfilter.org/conntrack-tools/	GPLv2	Used
dnsmasq	2.85	http://www.thekelleys.org.uk/dnsmasq/doc.html	GPLv2	Modified
dropbear	2024.85	https://github.com/mkj/dropbear	MIT	Modified
ebtables	2.0.10-4	https://git.netfilter.org/ebtables/	GPLv2	Modified
eventlog	0.2.10	https://github.com/balabit/eventlog	BSD	Used
expat	2.7.1	https://github.com/libexpat/libexpat	MIT	Used
ez-ipupdate	3.0.11b8	http://ez-ipupdate.com/	GPLv2	Modified
gettext	0.16	http://www.gnu.org/software/gettext/	GPLv2	Used
glib	2.37.7	http://www.gtk.org/	LGPLv2	Used
iproute2	2.6.33	https://github.com/shemminger/iproute2	GPLv2	Modified
iptables	1.4.21	https://git.netfilter.org/iptables/	GPLv2	Modified
jpegsrcc	v9a	http://www.iijg.org/	IJG	Used
json-c	0.13.1	https://github.com/json-c/json-c/downloads	MIT	Modified
libedit	20080712-2.11	http://pkgs.fedoraproject.org/repo/pkgs/libedit/libedit-20080712-2.11.tar.gz/	BSD	Modified
libffi	3.0.11	http://pkgs.fedoraproject.org/repo/pkgs/libffi/libffi-3.0.11.tar.gz/	MIT	Used
libiconv	1.11.1	http://www.gnu.org/software/libiconv/	LGPLv2	Modified
libnetfilter_conntrack	1.0.4	https://git.netfilter.org/libnetfilter_conntrack/	GPLv2	Used
libnetfilter_queue	1.0.2	https://git.netfilter.org/libnetfilter_queue/	GPLv2	Used
libnfnethlink	1.0.1	https://git.netfilter.org/libnfnethlink/	GPLv2	Used

libnl-tiny	0.1	https://github.com/openwrt/openwrt/tree/master/package/libs/libnl-tiny	GPLv2/LGPLv2.1	Used
libpcap	1.1.1	www.tcpdump.org	BSD	Used
libtool	2.4	http://www.gnu.org/software/libtool/	GPLv2	Used
libusb	1.0.9	https://sourceforge.net/projects/libusb/	LGPL 2.1	Used
libstrophe	0.10.0	https://github.com/strophe/libstrophe	GPLv2	Used
Linux/Arm Kernel	4.1.52			Modified
logrotate	3.22.0	https://launchpad.net/ubuntu/hardy/i386/logrotate/	GPLv2	Modified
mailsend	1.17b15	https://github.com/muquit/mailsend/	BSD	Modified
ncurses	5.7	http://ftp.gnu.org/pub/gnu/ncurses/	MIT	Modified
net-snmp	5.7.2	http://www.net-snmp.org/	ISC/BSD	Modified
ntfs-3g	2013.1.13	http://ntfs-3g.org	GPLv2/LGPLv2	Used
ntpclient	2007_365	http://doolittle.icarus.com/ntpclient/	GPLv2	Modified
openssl	3.2.0	http://www.openssl.org	OpenSSL	Modified
popt	1.16	http://rpm5.org/files/popt/	MIT	Modified
ppp	2.4.3	http://www.roaringpenguin.com/pppoe	GPLv2/BSD	Modified
pure-ftpd	1.0.50	http://pureftpd.org	ISC/BSD	Modified
radvd	1.8	http://www.litech.org/radvd/	BSD	Used
readline	8.2	http://cnswww.cns.cwru.edu/php/chet/readline/rltop.html	GPLv2	Used
samba	3.6.25	http://www.samba.org/samba/	GPLv3	Modified
sqlite	3460000	http://www.sqlite.org/	Public Domain License	Used
syslog-ng	4.7.1	https://github.com/balabit/syslog-ng	GPLv2	Used
tcpdump	4.99.4	http://www.tcpdump.org/	BSD	Used
udhcp	0.9.8	http://udhcp.busybox.net/	GPLv2	Modified
usb-modeswitch	2.1.0	http://www.draisberghof.de/usb_modeswitch/	GPLv2	Used
util-linux	2.21.2	https://github.com/karelzak/util-linux/	GPLv2	Used
wide-dhcpv6	20080615	https://sourceforge.net/projects/wide-dhcpv6/	BSD	Modified
zebra	0.93a	http://www.zebra.org/	GPLv2/LGPLv2	Used
zlib	1.3.1	https://github.com/madler/zlib	zlib	Used

Known issues

Modules	Issue	Risk Impact Information

Modifications in V5.42(ABYY.4.1)C0● **Feature Enhancement**

Modified Modules	Features Enhancement List
FCS	Based on V5.42(ABYY4.1)b1, Change to FCS version

Modifications in V5.42(ABYY.4.1)b1● **Bug Fixed**

Modified Modules	Bug Fixed List
Security	<ol style="list-style-type: none"> [#246928][CVE-2025-11845, CVE-2025-11846, CVE-2025-11847, CVE-2025-11848] Zyxel-SI-1638 [Vulnerability] Multiple potential null pointer dereference vulnerabilities in the CGI program [#246930][CVE-2025-13942、CVE-2025-13943] Zyxel-SI-1644 [Vulnerability] Command injection vulnerabilities in zupnp and zhttpd binaries in customized firmware

Modifications in V5.42(ABYY.4)C0● **Feature Enhancement**

Modified Modules	Features Enhancement List
FCS	Based on V5.42(ABYY4)b2, Change to FCS version

Modifications in V5.42(ABYY.4)b2● **Bug Fixed**

Modified Modules	Bug Fixed List
Security	<ol style="list-style-type: none"> [#240127][CVE-2025-8693] Zyxel-SI-1624 [Vulnerability] A post-authentication command injection vulnerability in

	the certificate upload CGI program of DX3300-T0 and VMG3925-B10B
	2. [#240128][CVE-2025-6599] Zyxel-SI-1621 [Vulnerability] Slow read DoS vulnerability on the zhttpd web server
	3. [#240129]Zyxel-SI-1612 Improper privilege management in VMG4005-B50A
	4. [#240131][CVE-2025-6599] Zyxel-SI-1616 [Vulnerability] Slow HTTP DoS vulnerability in the DX3301-T0

Modifications in V5.42(ABYY.4)b1

● Feature Enhancement

Modified Modules	Features Enhancement List
OMCI	[#234405] [eITS#250301374] DHCP ACK or request packets missing with the new FW PM7300-T0
GUI	[#234437] WEB GUI meets the request of Europe EAA (European Accessibility Act)
System	[#234756] [ENHANCE] Upgrade software packages
TR-069	[#235010] [eITS#250401710] PM7500-00 - Optical values are zero

● Bug Fixed

Modified Modules	Bug Fixed List
OMCI	[#233637] [Nokia] The operation status of uni port / vlan port / administrative is incorrect after a LOS event
Security	5. [#234603] [eITS#250400461] CVE-2024-6531: Bootstrap v4.6.2 Vulnerability 6. [#234627] [CVE-2024-8176] Zyxel-SI-1605 [Vulnerability] The libexpat open source library is vulnerable to DoS attacks through stack overflow
Other	[#233299] [eITS#250301839] Untagged service shows "reordered frames" in downstream direction.

Modifications in V5.42(ABYY.3)C0

● Feature Enhancement

Modified Modules	Features Enhancement List
FCS	Based on V5.42(ABYY3)b1, Change to FCS version

Modifications in V5.42(ABYY.3)b1

● Feature Enhancement

Modified Modules	Features Enhancement List
System	[#225479] [eITS#241101004][Konstanz] Feature request LAN follow WAN PM 7300-T0

● Bug Fixed

Modified Modules	Bug Fixed List
System	[#225834][eITS#241201160][NSBU] PM7300-T0 2.5LAN throughput not good

Modifications in V5.42(ABYY.2.3)C0

● Feature Enhancement

Modified Modules	Features Enhancement List
FCS	Based on V5.42(ABYY2.3)b1, Change to FCS version

Modifications in V5.42(ABYY.2.3)b1

● Bug Fixed

Modified Modules	Bug Fixed List
Security	[#220926] [CVE-2024-8748] [Zyxel-SI-1576] [Vulnerability] Unauthenticated buffer overflow in VMG8825-T50

Modifications in V5.42(ABYY.2.2)C0

● Feature Enhancement

Modified Modules	Features Enhancement List
FCS	Based on V5.42(ABYY2.2)b1, Change to FCS version

Modifications in V5.42(ABYY.2.2)b1

● Bug Fixed

Modified Modules	Bug Fixed List
Security	<ol style="list-style-type: none">1. [#213824] Zyxel-SI-1557 [Vulnerability] Unauthenticated heap buffer overflow in the libclinkc library2. [#213823] [CVE-2024-38266,38267,38268,38269][Zyxel-SI-1559][Vulnerability] Multiple authenticated buffer overflow vulnerabilities in VMG8825-T50

Modifications in V5.42(ABYY.2.1)C0

● Feature Enhancement

Modified Modules	Features Enhancement List
FCS	Based on V5.42(ABYY2.1)b1, Change to FCS version

Modifications in V5.42(ABYY.2.1)b1

● Bug Fixed

Modified Modules	Bug Fixed List
Security	<ol style="list-style-type: none">1. [#208301] Zyxel-SI-1536 [Vulnerability] Buffer overflow vulnerability in the "traceroute" command of DX3300-T1 CPE2. [#208302] Zyxel-SI-1506 [Vulnerability] Post-authentication buffer overflow in VMG3625-T50B

Modifications in V5.42(ABYY.2)C0

● Feature Enhancement

Modified Modules	Features Enhancement List
FCS	Based on V5.42(ABYY2)b3, Change to FCS version

Modifications in V5.42(ABYY.2)b3

● Feature Enhancement

Modified Modules	Features Enhancement List
OMCI	[ENHANCE][#199643] Changing SLID default value from empty to MAC address

● Bug Fixed

Modified Modules	Bug Fixed List
OMCI	<ol style="list-style-type: none"> [#200777][PON] When user change VLAN QinQ setting via OLT, user should reboot CPE then the new setting works [#200772][PON] When user change VLAN Translation setting via OLT, user should reboot CPE then the new setting works

Modifications in V5.42(ABYY.2)b2

● Feature Enhancement

Modified Modules	Features Enhancement List
OMCI	[#198665][eITS#230901139][OpenXS] S-VLAN and C-VLAN from the SFU PM 7300-T0.
Security	[#200581][eITS#230601286] Dnsmasq version upgrade.

● Bug Fixed

Modified Modules	Bug Fixed List
System	[#145927][System] Language list box only contains "English".

Modifications in V5.42(ABYY.2)b1

● Feature Enhancement

Modified Modules	Features Enhancement List
System	<ol style="list-style-type: none"> [#196583][PM7300-T0] Change default MTU size to 2000 [#196255][PM7300-T0][Generic][ETSI EN 303 645] The

	<p>consumer IoT device shall protect the confidentiality of critical security parameters that are communicated via remotely accessible network interfaces.</p> <p>3. [#196250][PM7300-T0][Generic] Console redirect/Zconsole monitor.</p> <p>4. [#196247][PM7300-T0][Generic] Support Web http redirect to https.</p> <p>5. [#195852][OPAL_Generic][PON platform] To encrypt GPON password in backup configuration</p>
--	--

● Bug Fixed

Modified Modules	Bug Fixed List

Modifications in V5.42(ABYY.1.3)C0

● Feature Enhancement

Modified Modules	Features Enhancement List
FCS	Based on V5.42(ABYY.1.3)b1, Change to FCS version

Modifications in V5.42(ABYY.1.3)b1

● Feature Enhancement

Modified Modules	Features Enhancement List
System	[#194269][eITS#230700881]Test PM 7300-T0

● Bug Fixed

Modified Modules	Bug Fixed List

Modifications in V5.42(ABYY.1.2)C0

● Feature Enhancement

Modified Modules	Features Enhancement List
FCS	Based on V5.42(ABYY.1.2)b1, Change to FCS version

Modifications in V5.42(ABYY.1.2)b1

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
OMCI	<ol style="list-style-type: none"> 1. [#190502][eITS#230500713]PM7300 - DS FEC values not as expected. 2. [#191328][eITS#230401106]PM7300-T0 - wrong Plug-in unit

Modifications in V5.42(ABYY.1.1)C0

● Feature Enhancement

Modified Modules	Features Enhancement List
FCS	Based on V5.42(ABYY.1.1)b1, Change to FCS version

Modifications in V5.42(ABYY.1.1)b1

● Feature Enhancement

Modified Modules	Features Enhancement List
OMCI	[#187041][eITS#230301538][OMCI]TC 6.3.7, 6.10.7 and 6.10.8 are failed

● Bug Fixed

Modified Modules	Bug Fixed List
Security	[#187478][Zyxel-SI-1464] [Vulnerability] OpenSSL multiple vulnerabilities for PM7300-T0
System	[#187593][eITS#221100592]PM7300-T0 - reset issue

Modifications in V5.42(ABYY.1)C0

● Feature Enhancement

Modified Modules	Features Enhancement List
FCS	Based on V5.42(ABYY.1)b2, Change to FCS version

Modifications in V5.42(ABYY.1)b2

● Feature Enhancement

Modified Modules	Features Enhancement List
OMCI	[#172175][OMCI]Support Upstream IGMP TCI and Upstream IGMP tag control

● Bug Fixed

Modified Modules	Bug Fixed List
Security	1. [#179017]Zyxel-SI-1441 [Vulnerability] Hidden SSID and symbolic Links in ftpd of AX7501-B0 2. [#177525]Zyxel-SI-1433 [Vulnerability] Buffer overflow vulnerabilities and command injection vulnerability for PM7300-T0
System	[#166039][eits 220400784]PM7300-T0 reboots

Modifications in V5.42(ABYY.1)b1

● Feature Enhancement

Modified Modules	Features Enhancement List
Security	[#166049][PM7300-T0] [Vulnerability] Infinite loop in BN_mod_sqrt() of OpenSSL when parsing certificates

● Bug Fixed

Modified Modules	Bug Fixed List
System	[#169718][eITS 220700081]PM7300-T0 #11 Blocked IGMP Leave message [#168516][eITS 220600052]PM7300-T0 - using Huawei OLT create IPoE interface fail
xPON	[#166035][eITS 220400339]Zyxel PM7300-T0 not IOP Huawei OLT
Security	[#166047][PM7300-T0] [Vulnerability][Generic] cleartext storage of sensitive information vulnerability

Modifications in V5.42(ABYY.0)C0

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List

Modifications in V5.42(ABYY.0)b8

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
Stress	1.#156046 ONT connect DUT(DX5301-B3) to test stress, but ONT's console will issue many warning logs and GUI can't login 2. # 154785 [Stress] LAN PC does not access GUI after Keep CPE idle time over 72 hours
System	1. #151962 When ONT is idle, it will happen many warnings that cause ONT to crash(Random)

Modifications in V5.42(ABYY.0)b7

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
Stress	1.#156046 ONT connect DUT(DX5301-B3) to test stress, but ONT's console will issue many warning logs and GUI can't login 2. # 154785 [Stress] LAN PC does not access GUI after Keep CPE idle time over 72 hours
TR-143	1.#156101 [TR-143] When download file over 3G, then execute GPV to get the value of "TotalBytesReceived" is only 2147483647
Log	1. #155967 Enable "OMCI" log, GUI will issue the LAN's warning log of OMCI continuously
System	1. #151962 When ONT is idle, it will happen many warnings that cause ONT to crash(Random)

Modifications in V5.42(ABYY.0)b6

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
System	1. #154679 [Stress] ONT happen call trace after overnight stress 2. #154680 [Console] Console print "aqr_phy.c [1011]: IOC_GET_link_state start" and "[ponmgr_lib_ioctl][196]:===Fail Exit===Couldn't open /dev/pon, fd = -1" continuously
TR-069	1. #154837 [TR-143] Perform HTTP Download Diagnostics, CPE work fail. 2. #151914 [TR-143] Upload diagnostic's TotalBytesSent & TotalBytesReceived can't execute normally
WebGui	1. #154808 [Log] Go System Monitor > Log, category does not 'TR-069' item.
OMCI	1. #151814 [GPON] When OLT disables ONU and becomes the O7 state, and then enables it, but ONT still keep in the O1 state
IGMP	1. #154673 [IGMP] LAN PC can not play IPTV.

Modifications in V5.42(ABYY.0)b5

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
System	1. # 152856 [System] ONT's NTP server cannot sync time and NTP First server doesn't match DST
TR-069	1. #151581 [TR-069] CPE didn't return fault code when server GPV "Device..." on TR-181 data model

WebGui	1. #147043 [PS] ONT's GUI does not match PS document. 2. #147046 [GUI] Go Maintenance > GPON, GUI pop out warn message incorrect. 3. #152852 [Maintenance] ONT should not support services of WAN side
OMCI	1. #147051 [OMCI] ONT firmware upgrade success but it does not switch to correct FW via OLT. 2. #146002 [OMCI] ONT will register fail when deactive/active ONT via OLT. 3.#146207 [OMCI] VLAN tranlation work fail 4.#146015 [OMCI] ONT will register fail when unplug/plug fiber line.

Modifications in V5.42(ABYY.0)b4

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
System	1.#151821 [System] In debug mode, after key in "atcr" command, Debug Flag cannot return to 0 2.#151585 [System] Log Setting page lack "TR-069" item. 3.#151514 [System] DST has some problems or not match ONU's settings 4.#145928 [System] Log page can't get any log information
WAN	1.#151504 [WAN] GUI must add a new WAN automatically after registered OLT successfully and get IP address by IP-HOST configuration 2.#151503 [WAN] OLT set a static IP address of IP-HOST, but ONU still use Dynamic IP address 3.#151506 [WAN] Unplug and plug PON line, the ONT's routing

	WAN of TR-069 cannot get IP address again 4.#146006 [OMCI] ONT will register fail via SLID.
WebGui	1.#151968 [GUI] The default SLID value does not match the correct hexadecimal value on the GPON page 2.#151743 [GUI] Login "admin" account and the wizard can change "Time zone", so GUI should open NTP setup page 3.#151507 [GUI] "System Info" page can't show IPv6 address information 4.#151498 [GUI] System Info - WAN status of Tx and Rx show empty values
TR-143	1.#151914 [TR-143] Upload diagnostic's TotalBytesSent & TotalBytesReceived can't execute normallygitk
LAN	1.#151502 [LAN] LAN DHCP function should be removed on LAN Setup page

Modifications in V5.42(ABYY.0)b3

● Feature Enhancement

Modified Modules	Features Enhancement List
TR069	1. Support TR069

● Bug Fixed

Modified Modules	Bug Fixed List
System	1. #145928 [System] Log page can't get any log information 2. #147214 [System] Upgrade config file to Rom-d fail via FTP. 3. #147200 [System] FW upgrade fail via ftp.
WAN	1. #146206 [OMCI] VLAN untage work fail 2. #146015 [OMCI] ONT will register fail when unplug/plug fiber line. 3. #146208 [OMCI] QinQ work fail
WebGui	1. #147018 [GUI] Some pages of the GUI are not removed. 2. #147047 [GUI] SLID value can not config success when it less than 72 hex.

	3. #147017 [GUI] GUI display incorrect web page after press F5. 4. #147043 [PS] ONT's GUI does not match PS document.
ExpressBoot	1. #147163 [ExpressBoot] Used ExpressBoot to upload config file to ROM-D. DUT's all setting change to default setting after reboot
IGMP	1. #145976 [IGMP] LAN PC can not play IPTV.

Modifications in V5.42(ABYY.0)b2

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
System	1.#145876 [System] Not support USB, but type USB command display "scsi_mod" information 2.#145877 [System] Enable SSH function, but use "Putty" tool can't connect 192.168.0.1 successfully 3. #145854 [System] The password length of admin does not match "Default Setting List" document 4.#145874 [System] The WiFi country code should be N/A in "Release Note". 5. #145962 [Remote MGMT] LAN PC does not access FTP/SSH.
WAN	4. #146051 [OMCI] ONT firmware upgrade fail via OLT. 5. #146006 [OMCI] ONT will register fail via SLID.
WebGui	5. #146070 [GUI] ONT only has one LAN port, but GUI display LAN2 and LAN3 ports in Traffic Status page 6. #145937 [Default Setting] ONT's GUI does not match Default setting document. 7. #145915 [PS] ONT's GUI does not match PS document.

Modifications in V5.42(ABYY.0)b1

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List