

ZYXEL

Software Release Note Switch XGS1250-12

Date: Jan. 08, 2025

Zyxel Switch XGS1250-12

V2.00(ABWE.1)C0 Release Note

Date: January 08, 2025

This document describes the features in the XGS1250 desktop product for its V2.00(ABWE.1)C0 release. Firmware upgrades may reset configuration options to factory default. Please backup your current configuration first before performing firmware upgrade.

* Hardware Rev.B1 supports firmware V2.00 and cannot be downgraded to V1.00.

Supported Platforms

| Support Platform | Firmware version |
|-------------------------|-------------------------|
| Zyxel XGS1250-12 | V2.00(ABWE.1)C0 |

New Feature and Enhancements

None

Bug fix

1. [eITS# 240401470] Switch disabled port will be linked up after a reboot or change speed/type or flow control.
2. [eITS # 241101371] Device may fail to load the startup configuration after the reboot.

Known Issue

None

Change History

- V2.00(ABWE.1) | 01/08/2025
- V2.00(ABWE.0) | 12/14/2023
- V1.00(ABWE.3) | 12/14/2022
- V1.00(ABWE.2) | 07/26/2022
- V1.00(ABWE.1) | 11/12/2021
- V1.00(ABWE.0) | 03/17/2021