

ZYXEL Mobile Router

Release Note

Firmware V1.60 Patch 0

November 14, 2025

Zyxel Nebula FWA515

V1.60(P0) C0 Release Note

Overview

This document provides firmware release information on Zyxel FWA515, new features and enhancements, bug fix, known issues and workarounds information for Release V1.60 Patch 0 C0.

Supported Platforms

- FWA515 V1.60(ACPZ.0)C0

New Features and Enhancements

N/A

Bug fix

1. [Vulnerability] Fix vulnerability - CVE-2025-6599.
2. An unexpected extra link is displayed between the FWA515 and the connected AP in the topology view.
3. After a device was added to an Organization/Site in Nebula, the local GUI login page did not display the "Managed by Nebula" message at the bottom as expected.
4. WLAN stations STA IP not show in Nebula Live Tool.
5. Tapping the QR code icon on the right side of the Nebula Control Center Status section did not display the expected QR code.

Known Issue

N/A

Limitation of Settings

N/A

Default Setting

1. Account for GUI:

Username	Password
Admin	Refer to device back label

2. Default URL: <http://192.168.1.1> is for the device GUI login