

# **Zyxel Switch GS1200-5HPv2**

## **V2.00(ABKN.0)C0 Release Note**

**Date: Dec. 17, 2020**

---

This document describes the features in the GS1200-5HPv2 product for its V2.00(ABKN.0)C0 release. Firmware upgrades may reset configuration options to factory default. Please backup your current configuration first before performing firmware upgrade.

### **Supported Platforms**

---

<b>Support Platform</b>	<b>Firmware version</b>
Zyxel GS1200-5HPv2	V2.00(ABKN.0)C0

### **New Feature and Enhancements**

---

1. Support port isolation
2. Support management VLAN
3. Support system up time

### **Bug fix**

---

#### **V1.00(ABKN.4)C0**

1. eITS#200700086  
**[IGMP]**IGMP control packet causes loop

## Known Issue

---

1. **[Firmware]** Downgrade from V1.00 patch 4 to V1.00 patch 3 and below versions will cause admin account unable to login. In the unlikely event of downgrading firmware, resetting to default can then login with default account and password.

## Change History

---

- V2.00(ABKN.0) | 12/17/2020
- V1.00(ABxx.4) | 01/10/2019
- V1.00(ABxx.3) | 11/10/2018
- V1.00(ABxx.2) | 10/25/2018
- V1.00(ABxx.1) | 07/27/2018
- V1.00(ABxx.0) | 11/08/2017