

ZYXEL

Software Release Note Switch GS1200v3

Date: Oct. 13, 2025

Zyxel Switch GS1200v3

V1.00(ACP_.2)C0 Release Note

Date: Oct. 13, 2025

This document describes the features in the GS1200v3 product for its V1.00(ACP_.2)C0 release. Firmware upgrades may reset configuration options to factory default. Please backup your current configuration first before performing firmware upgrade.

Note: The firmware only supports GS1200v3 series devices.

Supported Platforms

Support Platform	Firmware version
Zyxel GS1200-5v3	V1.00(ACPS.2)C0
Zyxel GS1200-8v3	V1.00(ACPT.2)C0
Zyxel GS1200-5HPv3	V1.00(ACPU.2)C0
Zyxel GS1200-8HPv3	V1.00(ACPV.2)C0
Zyxel GS1200-10v3	V1.00(ACPW.2)C0

New Feature and Enhancements

N/A

Bug fix

1. Fixed the web page abnormal display via HTTPS.
2. Fix the DUT may crash issue when change HTTP mode.
3. Fixed an issue where the port status displayed incorrect information in the State field when the LACP connection failed to establish.

Known Issue

1. In some scenarios, loop prevention in LAG may not work.

Change History

- V1.00(ACP_2) | 10/13/2025
- V1.00(ACP_1) | 08/22/2025