

ZYXEL

Software Release Note Switch GS1200v3

Date: Jun. 16, 2026

Zyxel Switch GS1200v3

V1.00(ACP_.4)C0 Release Note

Date: Jun. 16, 2026

This document describes the features in the GS1200v3 product for its V1.00(ACP_.4)C0 release. Firmware upgrades may reset configuration options to factory default. Please backup your current configuration first before performing firmware upgrade.

Note: The firmware only supports GS1200v3 series devices.

Supported Platforms

Support Platform	Firmware version
Zyxel GS1200-5v3	V1.00(ACPS.4)C0
Zyxel GS1200-8v3	V1.00(ACPT.4)C0
Zyxel GS1200-5HPv3	V1.00(ACPU.4)C0
Zyxel GS1200-8HPv3	V1.00(ACPV.4)C0
Zyxel GS1200-10v3	V1.00(ACPW.4)C0

New Feature and Enhancements

N/A

Bug fix

1. [CVE-2026-4795] Resolved unauthorized configuration file download without user authentication.
2. [CVE-2026-4795] Resolved the issue that allowed login using hashed credentials stored in the configuration.

3. The switch now automatically sends a new DHCP Discovery after the management VLAN ID is changed.
4. Resolved a login failure with passwords containing special characters.
5. Disable the console interface to enhance security.

Known Issue

1. In some scenarios, loop prevention in LAG may not work.

Change History

- V1.00(ACP_4) | 06/16/2026
- V1.00(ACP_3) | 04/24/2026
- V1.00(ACP_2) | 10/13/2025
- V1.00(ACP_1) | 08/22/2025